


# PREMIUM AUTOMOBILES



45, OR ROAD 1, SINGAPORE 408699


TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCL 579 Z

| S/N | NATURE OF JOBS                                                                                                                                                                    | ESTIMATED CHARGES   | SURVEYOR'S RECOMMENDATIONS |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------------------|
|     | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR KICK SENSOR. CHECK FUNCTION                                                                                                     | S/N \$ 360.00       | ✓                          |
|     | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 2,800.00         | 750                        |
|     | TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL TRIM AND RHS REAR DOOR.                                                                                                   | \$ 4,000.00         | 165                        |
| ④   | TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY.                                                                                                                               | S/N \$ 2,400.00     | ✓                          |
|     | TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                     | S/N \$ 520.00       | ✓                          |
| 5   | TO CARRY PRE/POST OUT DIAGNOSTIC CHECK.                                                                                                                                           | S/N \$ 384.00       | 192                        |
|     | <b>TOTAL LABOUR CHARGES</b>                                                                                                                                                       | <b>\$ 10,464.00</b> |                            |

# PREMIUM AUTOMOBILES



22, BIRI ROAD 1, SINGAPORE 408699

TEL: 6396 2323 FAX: 6841 1183

WWW.PREMIUMAUTOMOBILES.COM.SG / EMAIL: SALES@PREMIUMAUTOMOBILES.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCL 579 Z

|                       |                                               |     | DAMAGED PARTS & PRICES |         |
|-----------------------|-----------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                             | QTY | S/NETT                 | REMARKS |
| 1                     | REAR BUMPER <i>Repair</i>                     | 1 S | 3,268.00               | X       |
| 2                     | REAR BUMPER FIXING PARTS                      | 1 S | 273.00                 | X       |
| 3                     | REAR BUMPER CLOSING ELEMENT - RH              | 1 S | 81.00                  | X       |
| 4                     | REAR BUMPER SECURING STRIP                    | 1 S | 221.00                 | X       |
| 5                     | REAR BUMPER LOWER GUIDE SECTION - RH          | 1 S | 53.00                  | X       |
| 6                     | REAR BUMPER GUIDE SECTION SUPPORT - LH/RH     | 2 S | 66.00                  | X       |
| 7                     | REAR BUMPER BRACKET - RH                      | 1 S | 67.00                  | X       |
| 8                     | REAR BUMPER HOLDING STRIP - LH/RH             | 2 S | 126.00                 | X       |
| 9                     | REAR BUMPER GUIDE SECTION - CENTER            | 1 S | 100.00                 | X       |
| 10                    | REAR PARKING AID SENSOR                       | 1   | TBC                    | X       |
| 11                    | REAR PARKING AID SENSOR SEAL RING             | 2 S | 3.00                   | X       |
| 12                    | REAR WHEEL HOUSING LINER RH                   | 1 S | 275.00                 | X       |
| 13                    | ATTACHMENT PARTS FOR REAR WHEEL HOUSING LINER | 1 S | 22.00                  | X       |
| 14                    | REAR ALUMINIUM RIM - RH                       | 1 S | 1,749.00               | ✓       |
| 15                    | REAR WHEEL BEARING - RH                       | 1 S | 1,092.00               | ✓       |
| 16                    | SUSPENSION CONTROL ARM - LOWER RH             | 1 S | 905.00                 | ✓       |
| 17                    | REAR CONTROL ARM - RH                         | 1 S | 115.00                 | ✓       |
| 18                    | SUSPENSION CONTROL ARM - UPPER RH             | 1 S | 593.00                 | ✓       |
| 19                    | SIDE MEMBER TRIM ATTACHMENT PARTS             | 1 S | 89.00                  | ✓       |
| 20                    | SIDE MEMBER TRIM ADHESIVE TAPE                | 1 S | 16.00                  | X       |
| SUB TOTAL SPARE PARTS |                                               |     | 9,178.00               |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

REMARKS (X) = APPROVED, REMARKS (X) = NOT APPROVED  
PART PARTS ARE SPECIAL NETT.

= \$ 1,955

14/7 @ 10:59

CS spoken with Adhianto  
amend price in cost