

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0573/2021/TF
DATE : 13-Jul-21
WIP : 35106

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/7/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - Jy - 10 Sep 21

OWNER'S NAME : MR IKSAN KARIM
ADDRESS : 40B NASSIM HILL
#10-44
SINGAPORE 258474
TELEPHONE : HP +65 92329889
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100265115-10
VEHICLE NO : **SDH 8232 E**
MODEL CODE : A8L D4 3.0 TFSI QU
MODEL YEAR : 16/06/2011
ENGINE NO : CGW004294
CHASSIS NO : WAUZZZ4H5BN010527
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jul-21
PLACE OF ACCIDENT : JUNC OF BIDEFORE RD & CAIRNHILL RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDH 8232 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	\$ 300.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	2,000.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,400.00	\$ 1,200.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,600.00	\$ 1,200.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 11,314.00	\$ 3,372.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDH 8232 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,649.00	\$ 2,919.20
2	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 262.00	
3	FRONT BUMPER SPOILER	1	\$ 297.00	
4	FRONT WHEEL SPOILER - LH OUTER / INNER	2	\$ 81.00	
5	FRONT BUMPER FORM FILLER PIECE	1	\$ 127.00	
6	FRONT BUMPER CARRIER	1	\$ 1,157.00	
7	FRONT BUMPER CARRIER COVER	1	\$ 65.00	
8	FRONT BUMPER RETAINING BRACKET - LH / RH	2	\$ 30.00	
9	FRONT BUMPER GUIDE PIECE - LH	1	\$ 53.00	\$ 41.68
10	FRONT BUMPER TOP COVER	1	\$ 127.00	
11	CAUTION STICKER	1	\$ 14.00	
12	A/C STICKER	1	\$ 30.00	
13	FRONT BUMPER GRILLE - LH	1	\$ 421.00	\$ 336.40
14	HORN - LOW / HIGH TONE	2	\$ 483.00	
15	HORN BRACKET	1	\$ 128.00	
16	FRONT BUMPER SENSOR	1	TBC	
17	FRONT BUMPER SENSOR SEAL RING	4	\$ 6.00	
18	FRONT RADIATOR GRILLE	1	\$ 1,918.00	
19	FRONT RADIATOR GRILLE STRIKER PLATE - UPPER	1	\$ 131.00	\$ 104.80
20	FRONT RADIATOR GRILLE REINFORCEMENT - LH	1	\$ 49.00	\$ 38.80
SUB TOTAL SPARE PARTS		:	\$ 9,028.00	\$ 3,440.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDH 8232 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 3,440.88
21	FRONT FENDER - LH	1	\$ 1,842.00	\$ 1,473.60
22	FRONT FENDER ATTACHMENT PARTS	1	\$ 287.00	
23	FRONT FENDER BRACKET - LH	1	\$ 34.00	
24	FRONT FENDER BRACE - LH	1	\$ 850.00	\$ 680.00
25	FRONT FENDER BRACKET - FRONT LH	1	\$ 25.00	\$ 19.84
26	FRONT FENDER CONNECTING PIECE	1	\$ 243.00	\$ 194.00
27	FRONT BUMPER RETAINING BRACKET - LH	1	\$ 18.00	\$ 13.76
28	FRONT WHEEL HOUSING LINER - LH FRONT	1	\$ 296.00	
29	FRONT WHEEL HOUSING LINER - LH REAR	1	\$ 221.00	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 197.00	
31	FRONT HEADLIGHT - LH	1	\$ 5,107.00	\$ 4,085.60
32	FRONT HEADLIGHT CONTROL UNIT	1	\$ 1,116.00	
33	FRONT HEADLIGHT GAS DISCHARGE LAMP	1	\$ 416.00	
34	FRONT HEADLIGHT LIFT CYLINDER - LH	1	\$ 274.00	\$ 219.20
35	FRONT HEADLIGHT LIFT CYLINDER HOSE	1	\$ 109.00	
36	FRONT LOCK CARRIER	1	\$ 1,131.00	
37	BOLTS	12	\$ 117.00	
38	FRONT BUMPER SIDE MEMBER - LH	1	\$ 196.00	
39	FRONT ADDITIONAL COOLER - LH	1	\$ 807.00	
40	FRONT ADDITIONAL COOLER BRACKET - LH	1	\$ 157.00	
SUB TOTAL SPARE PARTS		:	\$ 13,443.00	\$ 10,126.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDH 8232 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 10,126.88
41	FRONT ADDITIONAL COOLER PUMP BRACKER - LH	1	\$ 179.00	
42	FRONT COOLANT PUMP	1	\$ 1,333.00	
43	FRONT COOLANT PUMP HOLDER - LH	1	\$ 69.00	
44	SOLENOID VALVE	1	\$ 347.00	
45	STOP BUFFER	1	\$ 17.00	
46	FRONT ADDITIONAL RADIATOR AIR GUIDE	2	\$ 79.00	
47	COOLANT	6	\$ 142.00	
48	FRONT RADAITOR AIR GUIDE	2	\$ 88.00	
49	FRONT NO. PLATE	S/N	\$ 60.00	
50	SUPPLEMENTARY		\$ 97.00	\$ 77.28
51	SUNDRIES		\$ 350.00	\$ 7.44
TOTAL SPARE PARTS			\$ 25,232.00	\$ 10,211.60
TOTAL LABOUR CHARGES			\$ 11,314.00	\$ 3,372.00
GRAND TOTAL			\$ 36,546.00	\$ 13,583.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-13/08/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0573/2021/TF 21-Jul-21 CHANG 1 of 1 SDH 8232 E AUDI A8L D4 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FONR BUMPER LOCKING CLIP	\$ 39.00	\$ 31.20
2	HEADLIGHT BRACKET	\$ 58.00	\$ 46.08
GRAND TOTAL		\$ 97.00	\$ 77.28

For Premium Automobiles Pte Ltd

Authorised Signature