

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0573/2021/TF
DATE : 13-Jul-21
WIP : 35106

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/7/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR IKSAN KARIM
ADDRESS : 40B NASSIM HILL
#10-44
SINGAPORE 258474
TELEPHONE : HP +65 92329889
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100265115-10
VEHICLE NO : **SDH 8232 E**
MODEL CODE : A8L D4 3.0 TFSI QU
MODEL YEAR : 16/6/2011
ENGINE NO : CGW004294
CHASSIS NO : WAUZZZ4H5BN010527
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jul-21
PLACE OF ACCIDENT : JUNC OF BIDEFORE RD & CAIRNHILL RD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDH 8232 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING. ATD	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ ✓ 450.00	300
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 2,000.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ ✓ 5,400.00	1200
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ ✓ 2,600.00	1200
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ ✓ 384.00	192
TOTAL LABOUR CHARGES		: \$ 11,314.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDH 8232 E

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>delhd.</i>	1	\$	3,649.00	✓	
2	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$	262.00	+	
3	FRONT BUMPER SPOILER ?	1	\$	297.00	?	
4	FRONT WHEEL SPOILER - LH OUTER / INNER <i>new</i>	2	\$	81.00	+	
5	FRONT BUMPER FORM FILLER PIECE ?	1	\$	127.00	?	
6	FRONT BUMPER CARRIER ?	1	\$	1,157.00	?	
7	FRONT BUMPER CARRIER COVER ?	1	\$	65.00	?	
8	FRONT BUMPER RETAINING BRACKET - LH / RH ?	2	\$	30.00	?	
9	FRONT BUMPER GUIDE PIECE - LH ?	1	\$	53.00	?	
10	FRONT BUMPER TOP COVER <i>new</i>	1	\$	127.00	+	
11	CAUTION STICKER ? <i>Not new</i>	1	\$	14.00	+	
12	A/C STICKER	1	\$	30.00	+	
13	FRONT BUMPER GRILLE - LH <i>Missing</i>	1	\$	421.00	✓	
14	HORN - LOW / HIGH TONE ?	2	\$	483.00	?	
15	HORN BRACKET ?	1	\$	128.00	?	
16	FRONT BUMPER SENSOR <i>new</i>	1		TBC	+	
17	FRONT BUMPER SENSOR SEAL RING <i>new</i>	4	\$	6.00	+	
18	FRONT RADIATOR GRILLE ?	1	\$	1,918.00	+	
19	FRONT RADIATOR GRILLE STRIKER PLATE - UPPER <i>new</i>	1	\$	131.00	+	
20	FRONT RADIATOR GRILLE REINFORCEMENT - LH	1	\$	49.00	+	
SUB TOTAL SPARE PARTS			:	\$ 9,028.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDH 8232 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,842.00	✓	
22	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 287.00	+	
23	FRONT FENDER BRACKET - LH ?	1	\$ 34.00	?	
24	FRONT FENDER BRACE - LH ?	1	\$ 850.00	?	
25	FRONT FENDER BRACKET - FRONT LH ?	1	\$ 25.00	?	
26	FRONT FENDER CONNECTING PIECE ?	1	\$ 243.00	?	
27	FRONT BUMPER RETAINING BRACKET - LH ?	1	\$ 18.00	?	
28	FRONT WHEEL HOUSING LINER - LH FRONT <i>new</i>	1	\$ 296.00	x	
29	FRONT WHEEL HOUSING LINER - LH REAR <i>new</i>	1	\$ 221.00	x	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 197.00	+	
31	FRONT HEADLIGHT - LH <i>Controlled</i>	1	\$ 5,107.00	✓	
32	FRONT HEADLIGHT CONTROL UNIT <i>new</i>	1	\$ 1,116.00	+	
33	FRONT HEADLIGHT GAS DISCHARGE LAMP <i>new</i>	1	\$ 416.00	+	
34	FRONT HEADLIGHT LIFT CYLINDER - LH <i>Damaged</i>	1	\$ 274.00	✓	
35	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>new</i>	1	\$ 109.00	+	
36	FRONT LOCK CARRIER <i>new</i>	1	\$ 1,131.00	+	
37	BOLTS	12	\$ 117.00	+	
38	FRONT BUMPER SIDE MEMBER - LH <i>new</i>	1	\$ 196.00	+	
39	FRONT ADDITIONAL COOLER - LH ?	1	\$ 807.00	?	
40	FRONT ADDITIONAL COOLER BRACKER - LH ?	1	\$ 157.00	?	
SUB TOTAL SPARE PARTS		:	\$ 13,443.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Ling

SURVEYED DATE

:

13/07/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT