



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0572/2021/ZK
DATE : 13-Jul-21
WIP : 34959

Denise.

\$15181.28

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/7/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHANG JIAN XIONG WILLIAM
ADDRESS : 274 YIO CHU KANG ROAD
#08-32
SINGAPORE 545688
TELEPHONE : HP +65 97358619
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210010967
VEHICLE NO : SJK 1133 K *SJK 1133 K.*
MODEL CODE : A5 SPORTBACK 2.0 TFSI S
MODEL YEAR : 29/1/2021
ENGINE NO : DEM 028990
CHASSIS NO : WAUZZZF50MA018600
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jul-21
PLACE OF ACCIDENT : RIVERSAILS CONDOMINIUM CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 1133 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LID.	S/N \$ 480.00	X
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$ 360.00	✓
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00 560	✓
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER. LHS REAR DOOR, LHS SILL PANEL TRIM AND REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00 1750	✓
5	TO RESPRAY LHS FRONT FENDER, LHD FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS REAR FENDER AND REAR BUMPER	\$ 6,200.00	6 x 550 = 3300 Handle = 100 Mirror = 150 3550
SUB TOTAL LABOUR CHARGES		\$ 13,840.00	✓

Handle
✓



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 1133 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW LHS REAR RIM.TO CARRY OUT WHEEL ALIGNMENT.	S/N S	280.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N S	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 14,312.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 1133 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT FENDER - LH <i>Repair</i>	1	\$ 1,060.00	X	
2	FRONT FENDER ATTACHMENT PART <i>3mm</i>	1	\$ 53.00	X	xnn
3	FRONT FENDER POP RIVET	1	\$ 20.00	+	xnn
4	FRONT FENDER CHROME TRIM <i>new</i>	1	\$ 164.00		130.8
5	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,884.00		3107.2
6	FRONT DOOR OUTER DOOR SEAL <i>new</i>	1	\$ 222.00		177.6
7	FRONT DOOR BONDING AGENT <i>3 new new</i>	1	\$ 49.00		
8	FRONT DOOR CLEANING SOLUTION	1	\$ 68.00		
9	FRONT DOOR APPLICATOR <i>3 new new</i>	1	\$ 8.00		
10	FRONT DOOR CATCH - LH	1	\$ 120.00		130.8
11	FRONT DOOR CHROME TRIM - LH <i>new new</i>	1	\$ 164.00		1549.6
12	FRONT MIRROR MOUNTING - LH <i>new</i>	1	\$ 1,937.00		
13	FRONT MIRROR CAP - LH <i>Repair</i>	1	\$ 289.00	X	
14	FRONT MIRROR GLASS - LH <i>new</i>	1	\$ 1,229.00	+	69.92
15	FRONT DOOR HANDLE COVER - LH <i>new</i>	1	\$ 88.00		69.92
16	HOUSING FOR DOOR HANDLE <i>new</i>	1	\$ 8.00	+	4.64
17	FRONT DOOR HANDLE LIGHT COVER - LH <i>new</i>	1	\$ 6.00	+	3107.2
18	REAR DOOR - LH <i>Dented</i>	1	\$ 3,884.00		177.6
19	REAR DOOR OUTER SEAL <i>new</i>	1	\$ 222.00		
20	REAR BONDING AGENT <i>2 new</i>	1	\$ 49.00		
SUB TOTAL SPARE PARTS		:	\$ 13,524.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 1133 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR CLEANING SOLUTION <i>3 new</i>	1	\$ 68.00	<i>+</i>	
22	REAR DOOR APPLICATOR	1	\$ 8.00	<i>+</i>	
23	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 173.00	<i>+</i>	
24	REAR DOOR CATCH - LH <i>new</i>	1	\$ 120.00	<i>+</i>	
25	REAR DOOR TRIM - LH <i>new</i>	1	\$ 869.00	<i>+</i>	<i>104.00 ✓</i>
<i>✱</i> 26	DOOR ATTACHMENT PARTS <i>ABC</i>	1	\$ 130.00	<i>+</i>	<i>169</i>
27	ADHESIVE TAPES <i>new</i>	1	\$ 169.6	<i>✓</i>	
28	REAR BUMPER <i>Regis</i>	1	\$ 2,451.00	<i>+</i>	
29	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 44.00	<i>+</i>	
30	REAR ALUMINIUM RIM - LH <i>new</i>	1	\$ 2,290.00	<i>+</i>	
31	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 275.00	<i>+</i>	
32	REAR WHEEL HOUSING LINER ATTACHEMENT PART <i>new</i>	1	\$ 169.00	<i>+</i>	
33	SUNDRIES <i>Not new.</i>	S/N	\$ 350.00	<i>+</i>	<i>✱</i>
TOTAL SPARE PARTS		:	\$ 20,683.00		
TOTAL LABOUR CHARGES		:	\$ 14,312.00		
GRAND TOTAL		:	\$ 34,995.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *14/07/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 08 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT