

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0572/2021/ZK
DATE : 13-Jul-21
WIP : 34959

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/7/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

8 days - ok - Jy - 23 Sep 21

OWNER'S NAME : MR CHANG JIAN XIONG WILLIAM
ADDRESS : 274 YIO CHU KANG ROAD
#08-32
SINGAPORE 545688
TELEPHONE : HP +65 97358619
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210010967
VEHICLE NO : **SJK 1133 K**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S
MODEL YEAR : 29/01/2021
ENGINE NO : DEM 028990
CHASSIS NO : WAUZZZF50MA018600
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 09-Jul-21
PLACE OF ACCIDENT : RIVERSAILS CONDOMINIUM CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 1133 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LID.	S/N \$	480.00		
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	S/N \$	360.00	\$	360.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$	560.00
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER. LHS REAR DOOR, LHS SILL PANEL TRIM AND REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,000.00	\$	1,750.00
5	TO RESPRAY LHS FRONT FENDER, LHD FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS REAR FENDER AND REAR BUMPER	\$	6,200.00	\$	3,550.00
SUB TOTAL LABOUR CHARGES		:	\$ 13,840.00	\$	6,220.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 1133 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 6,220.00
6	TO RENEW LHS REAR RIM.TO CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 14,312.00	\$ 6,412.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 1133 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - LH	1	\$ 1,060.00	
2	FRONT FENDER ATTACHMENT PART	1	\$ 53.00	
3	FRONT FENDER POP RIVET	1	\$ 20.00	
4	FRONT FENDER CHROME TRIM	1	\$ 164.00	\$ 130.80
5	FRONT DOOR - LH	1	\$ 3,884.00	\$ 3,107.20
6	FRONT DOOR OUTER DOOR SEAL	1	\$ 222.00	\$ 177.60
7	FRONT DOOR BONDING AGENT	1	\$ 49.00	
8	FRONT DOOR CLEANING SOLUTION	1	\$ 68.00	
9	FRONT DOOR APPLICATOR	1	\$ 8.00	
10	FRONT DOOR CATCH - LH	1	\$ 120.00	
11	FRONT DOOR CHROME TRIM - LH	1	\$ 164.00	\$ 130.80
12	FRONT MIRROR MOUNTING - LH	1	\$ 1,937.00	\$ 1,549.60
13	FRONT MIRROR CAP - LH	1	\$ 289.00	
14	FRONT MIRROR GLASS - LH	1	\$ 1,229.00	
15	FRONT DOOR HANDLE COVER - LH	1	\$ 88.00	\$ 69.92
16	HOUSING FOR DOOR HANDLE	1	\$ 8.00	
17	FRONT DOOR HANDLE LIGHT COVER - LH	1	\$ 6.00	\$ 4.64
18	REAR DOOR - LH	1	\$ 3,884.00	\$ 3,107.20
19	REAR DOOR OUTER SEAL	1	\$ 222.00	\$ 177.60
20	REAR BONDING AGENT	1	\$ 49.00	
SUB TOTAL SPARE PARTS		:	\$ 13,524.00	\$ 8,455.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 1133 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 8,455.36
21	REAR CLEANING SOLUTION	1	\$ 68.00	
22	REAR DOOR APPLICATOR	1	\$ 8.00	
23	REAR DOOR ATTACHMENT PARTS	1	\$ 173.00	
24	REAR DOOR CATCH -LH	1	\$ 120.00	
25	REAR DOOR TRIM - LH	1	\$ 869.00	
26	DOOR ATTACHMENT PARTS	1	\$ 130.00	\$ 104.00
27	ADHESIVE TAPES	1	\$ 212.00	\$ 169.60
28	REAR BUMPER	1	\$ 2,451.00	
29	REAR BUMPER GUIDE SECTION - LH	1	\$ 44.00	
30	REAR ALUMINIUM RIM - LH	1	\$ 2,290.00	
31	REAR WHEEL HOUSING LINER - LH	1	\$ 275.00	
32	REAR WHEEL HOUSING LINER ATTACHEMENT PART	1	\$ 169.00	
33	SUPPLEMENTARY		\$ 51.00	\$ 40.32
34	SUNDRIES	S/N	\$ 350.00	
TOTAL SPARE PARTS			\$ 20,734.00	\$ 8,769.28
TOTAL LABOUR CHARGES			\$ 14,312.00	\$ 6,412.00
GRAND TOTAL			\$ 35,046.00	\$ 15,181.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

bl-25/08/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0572/2021/ZK 03-Aug-21 CHANG 1 of 1 SKJ 1133 K AUDI A5 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	STONE CHIP GUARD - LH	\$ 51.00	\$	40.32
GRAND TOTAL		\$ 51.00	\$	40.32

(a) cut

For Premium Automobiles Pte Ltd

Authorised Signature