

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Department

ACCIDENT INVOLVING SLG7281E [YOUR INSURED] & SLD9600X [YOUR CLIENT] ON 12/07/2021.

ESTIMATED REPAIR COSTS FOR SLD9600X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by LKK Auto Consultants with final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

QTY	PARTS	AMOUNT	
1PC	REAR BOOT <i>St / Dent</i>	522.50	\$ 1,380.00 ✓
1PC	REAR BOOT NO. PLATE TOP CHROME <i>HN</i>		\$ 330.00 X
1SET	REAR BOOT NO. PLATE TOP CHROME CLIPS <i>HN</i>		\$ 20.00 X
1PC	REAR BOOT "HONDA" LOGO <i>HCC</i>	32.50	\$ 106.00 ✓
1PC	REAR BOOT "CITY" EMBLEM <i>HCC</i>	40.00	\$ 78.00 ✓
1PC	REAR BOOT "I-VTEC" EMBLEM <i>HCC</i>	42.00	\$ 88.00 ✓
2PCS	REAR BOOT LAMP LH / RH \$489.60 EACH <i>crack 410.40 x 2 = 820.80</i>		\$ 979.20 ✓
2SETS	REAR BOOT LAMP CLIPS @ \$20.00 EACH <i>HN</i>		\$ 40.00 X
1PC	REAR BOOT OPEN SWITCH <i>HN</i>		\$ 285.50 X
1PC	REAR BOOT INNER LOCK <i>Dent</i>	105.70	\$ 317.10 ✓
1PC	REAR BOOT INNER LOCK CABLE <i>HN</i>		\$ 89.00 X
1PC	REAR BOOT STRIKER LOCK <i>St</i>	50.80	\$ 104.00 ✓
1PC	REAR BOOT INNER TRIM <i>HN</i>		\$ 413.92 X
1SET	REAR BOOT INNER TRIM CLIPS <i>HN</i>		\$ 20.00 X
1PC	REAR BOOT WEATHERSTRIP RUBBER <i>damaged</i>	144.20	\$ 243.20 ✓
2PC	REAR BOOT HINGE LH / RH @ \$255.98 EACH EACH <i>HN</i>		\$ 511.96 X
1SET	REAR BOOT RUBBER STOPPERS <i>SLC</i>		\$ 120.00 X
1PC	REAR BUMPER <i>Dent</i>	463.70	\$ 898.00 ✓
1SET	REAR BUMPER CLIPS <i>HCC</i>	SN 15.00	\$ 20.00 ✓ SN
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$57.50 EACH <i>SLC</i>		\$ 115.00 X
2PC	REAR BUMPER REFLECTOR LH / RH @ \$194.58 EACH <i>HN</i>		\$ 389.16 X
1PC	REAR END PANEL <i>Buc</i>	481.20	\$ 782.49 ✓
1PC	REAR END PANEL TOP GARNISH <i>damaged / mondy crack</i>		\$ 342.84 ✓ 199.50
1SET	REAR END PANEL TOP GARNISH CLIPS <i>HCC</i>	SN 15.00	\$ 20.00 ✓ SN
2PCS	REAR FENDER LH / RH @ \$ 1282.80 EACH <i>o/s HN N/S rev</i>		\$ 2,565.60 2565.60 X
2PCS	REAR FENDER INNER TRIM LH / RH @ \$367.70 EACH <i>SLC</i>		\$ 735.40 X
2SETS	REAR FENDER INNER TRIM BOARD CLIPS <i>HN</i>		\$ 20.00 X
2PCS	REAR FENDER SHIELD LH / RH @ \$204.84 EACH <i>HN</i>		\$ 409.68 X
2SETS	REAR FENDER INNER SHIELD CLIPS <i>HN 425.00 x 2 = 850.00</i>		\$ 30.00 X
2PCS	REAR FENDER TAIL LAMP LH / RH @ \$774.60 EACH <i>crack mondy</i>		\$ 1,549.20 ✓
2PCS	REAR FENDER TAIL LAMP PANEL LH / RH @ \$295.00 EACH <i>o/s rev Dent</i>		\$ 590.00 ✓ 1295.00
1PC	REAR KEYLESS ENTRY SENSOR <i>mondy broken</i>	<i>HN</i>	\$ 238.40 ✓

1PC	REAR KEYLESS ENTRY BUZZER <i>money 5t / white</i>	\$ 229.41	✓
1PC	REAR SPARE WHEEL PANEL <i>new</i>	\$ 1,120.40	X
1PC	REAR SPARE WHEEL PANEL TOP WOODEN BOARD <i>broken 150.00</i>	\$ 512.90	✓
1PC	REAR SPARE WHEEL PANEL TOP TRIM <i>new</i>	\$ 385.00	X
2PCS	REAR SPARE WHEEL SIDE PANEL LH / RH @ \$394.71 EACH <i>new</i>	\$ 789.42	X
1PC	REAR EXHAUST PIPE <i>new</i>	\$ 804.46	X
1SET	REAR EXHAUST MOUNTING <i>new</i>	\$ 110.00	X

466571
373256

PARTS SUM: \$ 17,783.24
 PARTS LESS 20%: \$ 3,556.65
 PARTS TOTAL: \$ 14,226.59

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE & HOLDER <i>new</i>	\$ 100.00	X
*	TO SUPPLY REVERSE CAMERA <i>new</i>	\$ 500.00	X
*	TO SUPPLY 1 SET REVERSE SENSOR <i>Don</i>	\$ 300.00 250/-	
*	TO SUPPLY REAR END PANEL SEALANT <i>new</i>	\$ 80.00	40/-
*	TO SUPPLY REAR WINDSCREEN SEALANT <i>new</i>	\$ 80.00	X
*	TO SUPPLY SPARE WHEEL PANEL SEALANT <i>new</i>	\$ 80.00	X
*	TO SUPPLY SPARE WHEEL QUARTER PANEL SEALANT <i>new</i>	\$ 80.00	X
*	TO SUPPLY SPARE WHEEL SIDE PANEL SEALANT <i>new</i>	\$ 80.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 80/-	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00 1000/-	
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00 900/-	
*	TO REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 250.00	new
*	TO REFIT REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00 60/-	
*	TO CHECK REAR CHASSIS ALIGNMENT	\$ 200.00	new
*	TO REFIT EXHAUST SYSTEM AND CHECK FOR LEAKAGE	\$ 250.00	new
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS <i>2150.00</i>	\$ 200.00 30/-	
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	new
*	TO REFIT NEW REVERSE SENSORS ON NEW REAR BUMPER	\$ 200.00 40/-	
*	TO REFIT NEW REVERSE CAMERA ON NEW REAR BOOT	\$ 200.00	new
*	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	\$ 500.00 40/-	

14/07/2021 @ 17:00hr

LABOUR & S/N TOTAL: \$ 8,700.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 22,926.59

NA Andrew
L/S new 6 days
1 year
check papers.
L/KC Andrew
 6202.56
 L/S 4,900/-