

(P.V.S. NEW WORKS AS A SET. NOT SEPARATE.)

CT1
SJH 8008R NA2

AP
Automotive Services

AT AUTOMOTIVE SERVICES PTE LTD
POB 2020228004
BUCK ROOM
TAMPINE 5 STREET 51 #01 202
SINGAPORE 530040
TEL 9784 4465
FAX 9787 4884

Estimation

Date: 17/11/2021
Vehicle: SJH 8008R
Make/Model: BMW 520D
Chassis No: WBAJC320X0G580963

No.	Description	Unit	Unit Price	Amount
Parts Replacement				
1	REAR WINDSCREEN / CRK	1		\$ 1099 600
2	REAR WINDSCREEN MOULDING / NPL	1		\$ 157
3	REAR BOOTLID / DEF	1		\$ 1660 1,000
4	REAR BOOTLID LOGO / NPL	1		\$ 72
5	REAR BOOTLID EMBLEM / NPL	1		\$ 71
6	REAR BOOTLID OPNER ? / DEF	1		\$ 107
7	REAR BOOTLID NUMBER PLATE LAMP ? / CRK	2	45.30	\$ 90.60
8	REAR BOOTLID REVERSE CAMERA ? / DEF	1		\$ 367 300
9	REAR BOOTLID LAMP L+R R / CRK L? XSVL SCR 1	2	372	\$ 744 744
10	REAR BOOTLID LAMP SEAL L+R ? XNN	2	37	\$ 74
11	REAR BOOTLID LOCK / DEF	1		\$ 220
12	REAR BOOTLID LOCK COVER / DEF	1		\$ 80
13	REAR BOOTLID INNER SWITCH BUTTON ? / DEF	1		\$ 75
14	REAR BOOTLID INNER SWITCH ASSY ? XSVL	1		\$ 123
15	REAR BOOTLID INNER TRIM / DEF	1		\$ 117
16	REAR BOOTLID INNER TRIM STOPPER ? XSVL	2	39	\$ 78
17	REAR BOOTLID HINGE L+R ? XSVL	2	121	\$ 242
18	REAR BOOTLID HINGE COVER L+R ? XSVL / DEF	2	79	\$ 158
19	REAR BOOTLID WEATHERSTRIP / DEF	1		\$ 119
20	REAR TAILLAMP L+R R / CRK L? / SCR	2	653.50	\$ 1307 1307
21	REAR TAILLAMP PANEL L+R ? / DD	2	267.150	\$ 534.300
22	REAR TAILLAMP SEAL L+R ? XNN	2	51	\$ 102
23	REAR TAILLAMP CLIPS L+R ? / NPL	2	16	\$ 32
24	REAR TAILLAMP SIDE GARNISH L+R ? XNN	2	80	\$ 160
25	REAR BUMPER / CRK	1		\$ 1581 1,300
26	REAR BUMPER REVERSE SENSOR SET ? / NPL	4	241.750	\$ 967 600
27	REAR BUMPER REVERSE SENSOR WIREHARNESS ? XSVL	1		\$ 309
28	REAR BUMPER CENTER CHROME / CRK	1		\$ 257
29	REAR BUMPER REFLECTOR L+R ? XSVL	2	49	\$ 98
30	REAR BUMPER REINFORCEMENT BAR ? / DD	1		\$ 776 650
31	REAR BUMPER REINFORCEMENT BAR BRACKET L+R ? / DD	2	95	\$ 190
32	REAR BUMPER REINFORCEMENT CARRIER ? / DEF	1		\$ 112
33	REAR BUMPER CENTER BRACKET ? / DEF	1		\$ 148 150
34	REAR BUMPER KICK SENSOR STRIP ? XSVL	1		\$ 107
35	REAR BUMPER KICK SENSOR DETECTOR ? XSVL	1		\$
36	REAR BUMPER KICK SENSOR ECU MODULE ? XSVL	1		\$ 1134
37	REAR BUMPER RETAINER SIDE L+R R / CRK L? / CRK	2	40	\$ 80

250 ✓

13,745
8,551

~~Handwritten scribbles and marks, possibly including the letters 'X' and 'R'.~~

— photo?

{ Local repair
\$500 (SN) ✓

~~not~~ Local repair
\$300 (SH) ✓

Less 10% ✓

60 ✓
50 ✓

540

8	REAR DOOR TRIM CLIPS SET ? XNN	1	120	\$	120.00
9	REAR BUMPER CLIPS SET ✓ NPL	1	120	\$	120.00
10	REAR NUMBER PLATE ✓ CCI	1	100	\$	100.00
					155
	Total		\$	1300	1,200.00

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	2000	\$ 1,200 2,000.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1800	\$ 1,000 1,800.00
3	TO RNR REAR WINDSCREEN	1	400	\$ 120 400.00
4	TO RNR REAR EXHAUST	1	? 400	\$ 80 250.00
5	TO CHECK WIRING AND HEADLAMP FOCUS	1	XNN 250	\$ 120.00
6	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	30 120	\$ 120.00
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	30 120	\$ 400.00
8	TO RNR REAR INNER TRIM AND UPHOISTERY	1	150 120	\$ XNN 120.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	? 120	\$ X NN 120.00
10	TO RNR UNDERCARRIAGE	1	? 120	\$ X NN 120.00
11	TO CHECK WHEEL BALANCING	1	X NN 200	\$ X NN 200.00
12	TO CHECK WATER LEAK	1	? 500	\$ 80 500.00
15	TO RNR FUEL TANK	1	? 800	\$ 250 800.00
16	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	250	\$ 50 250.00
17	TO RNR REAR TAILGATE MECHANISM	1	? 250	\$ 30 250.00
18	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	120	\$ 50 120.00
19	TO PERFORM RUST PROOFING	1	? 120	\$ X NN 120.00
20	TO RNR REAR FRONT DOOR MECHANISM	1	? 600	\$ X NN 600.00
21	TO RNR KICK SENSOR AND TEST FUNCTION			
Total Labour		\$		8,690.00
Parts Replacement Amount		\$		1,200.00
Total Amount		\$		9,890.00

NAT CLK
15/7/2021
LIS
4 DAYS
(CHECK ITEM PHOTO)
OTHER REFERENCE PHOTO)

PARTS \$24,537.00
LESS 5% \$23,310.15 — Less 10% ✓
SINETT \$ 695.00
LABOUR \$ 2,820.00
\$26,825.15
LESS LIS 20% \$21,460.12
LIS TOTAL \$21,450.00 / 5 DAYS