

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Jul-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S

1 pc	Rear n/s fender	\$ 1,205.00	DD
1 pc	Rear n/s fender inner shield	\$ 120.00	DEF
1 pc	Rear windscreen moulding	\$ 87.00	NEC
1 pc	Rear bumper	\$ 696.00	CRK
1 pc	Rear bumper side bracket n/s	\$ 29.00	?
1 pc	n/s rocker panel garnish	\$ 286.00	XR
1 pc	Wheel cover	\$ 116.00	SCR

\$ 2,539.00

\$ 225.30

\$ 2,313.70

### S/NETT

1 set	Rear bumper clips	\$ 48.00	NEC
1 set	Rear fender n/s inner shield clips	\$ 38.00	NEC
1 pc	Rear n/s fender sticker	\$ 60.00	NEC
1 pc	Sealant	\$ 50.00	40
1 set	n/s rocker panel garnish clips	\$ 38.00	xnn
1 set	N/s door sticker	\$ 100.00	xnn

Sundry \$ 50.00 xnn

To dismantle and refit rear windscreen \$ 120.00 /

To dismantle / refit reverse sensor to new bumper and reset to the same \$ 120.00 30

To check wheel alignment \$ 160.00 xnn? show receipt

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 xnn

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc \$ 950.00 450

To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, n/s rocker panel garnish \$ 800.00 450

To apply rustproofing on the repaired and replaced panels. \$ 180.00 50

\$ 5,207.70

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT  
INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK  
15/7/2021 1730  
LIS  
4/5 Days  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS