

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S

1 pc	Rear n/s fender	\$ 1,205.00	DD
1 pc	Rear n/s fender inner shield	\$ 120.00	DEF
1 pc	Rear windscreen moulding	\$ 87.00	NEL
1 pc	Rear bumper	\$ 696.00	CRK
1 pc	Rear bumper side bracket n/s	\$ 29.00	XSVL
1 pc	n/s rocker panel garnish	\$ 286.00	R
1 pc	Wheel cover	\$ 116.00	SCR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Less 10%
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S/NETT

1 set	Rear bumper clips	\$ 48.00	NEL
1 set	Rear fender n/s inner shield clips	\$ 38.00	NEL
1 pc	Rear n/s fender sticker	\$ 60.00	NEL
1 pc	Sealant	\$ 50.00	40
1 set	n/s rocker panel garnish clips	\$ 38.00	XNN
1 set	N/s door sticker	\$ 100.00	XNN

Sundry \$ 50.00 XNN

To dismantle and refit rear windscreen \$ 120.00

To dismantle / refit reverse sensor to new bumper and reset to the same \$ 120.00 30

To check wheel alignment \$ 160.00 XNN? show XNN help

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 XNN

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc \$ 950.00 450

To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, n/s rocker panel garnish \$ 800.00 450

To apply rustproofing on the repaired and replaced panels. \$ 180.00 50

\$ 5,207.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK
15/7/2021 1730
LIS

48 Days
CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS

PARTS \$2,224.00
LESS 10% \$2,001.60

S/NETT \$ 186.00

LABOUR \$1,100.00

TOTAL \$3,287.60

LESS 4% \$2,630.08
20%

LIS TOTAL \$2,600.00