



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM LEE KENG	Cust No/Name	/LIM LEE KENG
83 YISHUN STREET 81	Reg No/Reg Date	SMR5570P / 14/01/202
#09-04	Date In/Mileage	/ 0
SINGAPORE 768446	Chassis No	KNAF3416ML5063037
Contact No Mobile: 94523785	Engine No	G4FGKH739739
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	15/07/2021/ 12:55	BLC	442 / CocoLu	36100			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2800.00
RENEW FRT DOOR LH, REAR DOOR LH, SIDE SILL LH, WINDMIRROR LH								
REAR BUMPER,REPAIR REAR FENDER LH								
E PNT88000								180.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								180.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
E PNT98000								2880.00
SPRAY PAINT FOR FRT DOOR LH, REAR DOOR LH, SIDE SILL LH, REAR BUMPER								
REAR FENDER LH, WINDMIRROR LH								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY								30.00
TRANSFER REAR LEFT RIM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M SUNDRY								480.00
SUPPLY REAR RIM								
M	PANEL ASSY-FRONT DOOR,LH			1.00	1277.00	00.00		1277.00
M	PANEL ASSY-REAR DOOR,LH			1.00	1377.00	00.00		1377.00
M	PANEL-SIDE SILL OUTRER,LH			1.00	1208.00	00.00		1208.00
M	COVER-RR BUMPER			1.00	651.00	00.00		651.00
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	00.00		25.00
M	COVER-RR BUMPER FOG LAMP,LH			1.00	19.00	00.00		19.00
M	LAMP ASSY-SIDE T/SIGNAL,LH			1.00	181.00	00.00		181.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM LEE KENG	Cust No/Name	/LIM LEE KENG
83 YISHUN STREET 81	Reg No/Reg Date	SMR5570P / 14/01/202
#09-04	Date In/Mileage	/ 0
SINGAPORE 768446	Chassis No	KNAF3416ML5063037
Contact No Mobile: 94523785	Engine No	G4FGKH739739
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	15/07/2021/ 12:55	BLC	442 / CocoLu	36100			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	COVER-RR BUMPER LWR				1.00	241.00	00.00	241.00
M	MIRROR ASSY-OUTSIDE RR VIEW,LH				1.00	559.00	00.00	559.00
M	MOULDING ASSY-FRT DR FRAME,LH				1.00	37.00	00.00	37.00
M	MOULDING ASSY-RR DR FRAME,LH				1.00	44.00	00.00	44.00
M	BLACK TAPE-FR DR RR,LH				1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FR,LH				1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FRAME RR OTR,				1.00	8.00	00.00	8.00
Estimate								

Estimate

Confirm & accepted by

7% GST on	Nett	12,633.00
	12633.00	884.31
Total Payable		13,517.31

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.