



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: [claims01@autoinsure.com.sg](mailto:claims01@autoinsure.com.sg)  
W: [www.autoinsure.com.sg](http://www.autoinsure.com.sg)  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SMD4575G (SIEW)**

Your Ref: **SHD6126R**

Date: **10-Jul-21**

BY EMAIL ONLY  
([claims01@autoinsure.com.sg](mailto:claims01@autoinsure.com.sg))

**ATTENTION: MOTOR CLAIMS DEPT**

Email : [motor\\_claims@first-insurance.com.sg](mailto:motor_claims@first-insurance.com.sg)

**First Capital Insurance Limited**

6 Raffles Quay #21-00  
Singapore 048580

Assessed Vehicle No : **SMD4575G**  
Car Make and Model : **HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)**  
Date of Accident : **8-Jul-21**  
Date of Assessment : **10-Jul-21**

We have carried out a physical assessment of SMD4575G at our workshop Auto Insure Pte Ltd sustained damages to the RH & REAR portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the RH & REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**  
Adjusted Amount : **\$ 15,961.49**  
Est. Repair Days : **10**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **SMD4575G**

Your Ref: **SHD6126R**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
		<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>		
1	1	ROCKER PANEL RH		REPAIR
2	1	REAR DOOR RH		\$ 1,750.60
3	1	REAR DOOR LOCK RH		\$ 559.30
4	1	REAR DOOR WINDOW REGULATOR RH		\$ 454.90
5	1	REAR DOOR INNER TRIM BOARD RH		\$ 1,470.50
6	1	REAR DOOR INNER WEATHERSTRIP RH		\$ 296.10
7	1	REAR FENDER RH		REPAIR
8	1	REAR FENDER LH		REPAIR
9	1	REAR TAIL LAMP RH		\$ 752.60
10	1	REAR TAIL LAMP LH		\$ 752.60
11	1	REAR BOOT LID		REPAIR
12	1	REAR BOOT LID LOGO H		\$ 94.70
13	1	REAR BOOT LID EMBLEM ELANTRA		\$ 86.30
14	1	REAR BOOT LID EMBLEM S		\$ 58.30
15	1	REAR BOOT LID REVERSE LAMP RH		\$ 693.20
16	1	REAR BOOT LID REVERSE LAMP LH		\$ 693.20
17	1	REAR BOOT LID LOCK		\$ 365.10
18	1	REAR BOOT LID LOCK STRIKER		\$ 39.40
19	1	REAR BUMPER		\$ 881.50
20	1	REAR BUMPER REFLECTOR RH		\$ 115.60
21	1	REAR BUMPER REFLECTOR LH		\$ 115.60
22	1	REAR BUMPER LOWER COVER		\$ 524.90
23	1	REAR BUMPER SIDE MUDFLAP RH		\$ 87.10
24	1	REAR BUMPER SIDE MUDFLAP LH		\$ 87.10
25	1	REAR BUMPER SIDE RETAINER RH		\$ 78.90
26	1	REAR BUMPER SIDE RETAINER LH		\$ 78.90
27	1	REAR BUMPER REINFORCEMENT		\$ 366.20
28	1	REAR BOOT LID WEATHERSTRIP		\$ 270.50
29	1	REAR END PANEL		\$ 985.60
30	1	REAR END PANEL GARNISH		\$ 183.90
31	1	REAR FLOOR PANEL		REPAIR
32	1	REAR WHEEL RIM RH		\$ 789.50
33	1	REAR WHEEL RIM LH		\$ 789.50
			SUB TOTAL	\$ 13,421.60
			LESS 20%	\$ 2,684.32
			TOTAL AMOUNT	\$ 10,737.28

Our Ref: **SMD4575G**

Your Ref: **SHD6126R**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR WINDSCREEN MOULDING		\$ 150.00
2	1	REAR WINDSCREEN SEALANT		\$ 100.00
3	1	REAR NUMBER PLATE & HOLDER		\$ 80.00
4	1	REAR BUMPER CLIPS		\$ 60.00
5	1 SET	REAR BUMPER REVERSE SENSORS		\$ 350.00
			SUB TOTAL	\$ 740.00
			TOTAL PARTS COST	\$ 11,477.28

Our Ref: **SMD4575G**

Your Ref: **SHD6126R**

S/NO	DESCRIPTION	EST. BY WORKSHOP
	<b>LABOUR &amp; PAINTWORK</b>	
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 900.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 80.00
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ 250.00
4	TO REMOVE & REFIT REAR DOOR MECHANISM RH	\$ 150.00
5	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS	\$ 100.00
6	TO REMOVE & REFIT UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$ 120.00
7	TO REMOVE & REFIT REAR WHEEL RIM & TYRE RH & LH	\$ 100.00
8	TO CONDUCT WHEEL ALIGNMENT & BALANCING	\$ 100.00
9	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 1,400.00
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 80.00
11	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 50.00
12	TO VACUUM, WAXING & CLEAN	\$ 60.00
13	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00
	TOTAL BEFORE GST	\$ 14,917.28
	GST 7%	\$ 1,044.21
	TOTAL (PARTS & LABOUR):	\$ <b>15,961.49</b>

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 15,961.49** for part by part with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director