

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
61 Sep @ 4150h
Returning After Paint
4 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **14.07.2021**

Accident Date : 12.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Vellfire" Reg. No. SMV5171L Claiming Against Your Insured Reg. No. SKW3194C			
1pc	Tailgate <i>1956</i>		<i>Pr</i> 2,245.00 ✓
1pc	Tailgate Glass Moulding		<i>me</i> 92.00 ✓
1pc	Tailgate Badge Vellfire		<i>me</i> 75.00 ✓
4pcs	Tailgate Outer Garnish Clips	7.31	<i>me</i> 29.24 X
1pc	Tailgate Weatherstrip <i>319.50</i>		<i>me</i> 356.00 ✓ <i>John</i>
1pc	Tailgate Inner Rubber with Sensor LH		<i>me</i> 877.00 X
1pc	Tailgate Trim Board		<i>me</i> 705.00 ✓
1pc	Tailgate Trim Board Sticker(info)		<i>me</i> 50.00 ✓
12pcs	Tailgate Trim Board Clips	7.31	<i>me</i> 87.72 ✓
1pc	Tailgate Inner Switch Outer Cover		<i>me</i> 72.00 ✓
1pc	Rear Bumper <i>869.80</i>		<i>me</i> 1,952.00 ✓
10pcs	Rear Bumper Clips	7.31	<i>me</i> 73.10 ✓
1pc	Rear Bumper Bracket LH		<i>me</i> 112.20 X
1pc	Rear Bumper Sponge		<i>me</i> 265.00 X
1pc	Rear Bumper Retainer LH		<i>me</i> 103.45 X
1pc	Rear Bumper Reflector LH		<i>me</i> 72.30 ✓
1pc	Rear Bumper Tow Cover LH		<i>me</i> 29.90 ✓
1pc	Rear Bumper Lower Cover LH		<i>me</i> 255.00 X
2pcs	Rear Bumper Sensors <i>pr @ 265</i>	446.20	<i>me</i> 892.40 ✓
1pc	Rear Bumper Auto Boot Sensor		<i>me</i> 215.00 X
1pc	Rear Bumper Buzzer		<i>me</i> 89.00 X
1pc	End Panel		<i>me</i> 871.70 X
Less 25%			9,520.01
			2,380.00
			7,140.01
	Tailgate Glass Sealant		<i>me</i> 40.00 SN
	Tailgate Glass Sealer		<i>me</i> 30.00 SN ✓
	Tailgate Glass Fastener		<i>me</i> 30.00 SN
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		150.00 <i>bol</i>
	To Dismantle / Refit Tailgate Glass		160.00 <i>1201</i>
	To Supply End Panel Body Sealant		60.00 <i>301</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 <i>bol</i>

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **14.07.2021**

Accident Date : 12.07.2021

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Vellfire" Reg. No. SMV5171L Claiming Against Your Insured Reg. No. SKW3194C		
		B/F	7,720.01
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Rewiring etc.		120.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Rear Chassis Member, Floor Panel, Inner Panel etc. Cnt, Weld End Panel and Parts Replacement		900.00 <i>6001</i>
	To Respray Affected Areas		850.00 <i>500d</i>
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas.		<i>nn</i> 400.00 <i>X</i>
	Total :		<u><u>9,990.01</u></u>

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: