



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107566

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 03/11/2021
Reference CC4/FCI21007684/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKM 991R

Insured Veh. SBS 6485X

Claim No. D21002044MFBP

Policy No. D-20096309MFBP

Accident Date 04/07/2021

Inspection Date 15/07/2021

Description	Total
Survey Inspection	301.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	301.00
GST (7%)	21.07
Grand Total	322.07

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21007684/R1ra3q2 Date: 03/11/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6485X	Veh. Inspected	SKM 991R	
Policy No.	D-20096309MFBP	Coverage (\$)	0.00	
Claim No.	D21002044MFBP	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	15/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XF 2.0P 200PS	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SAJBB4AX7JCY70108	Colour	BLACK	
Odometer	45013 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/07/2021	Inspection Date	15/07/2021	
Survey held at	45 LENG KEE			
Repairer	WEARNES AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 991R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR COVER RH XF R (SN)	TO REPAIR SEE LABOUR	180.50	-
1	MIRROR DOOR RH (SN)	SCRATCHED	1,177.80	1,060.02
1	LAMP (SN)	SCRATCHED	163.70	147.33
1	FINISHER -VENT (SN)	NOT NECESSARY	275.10	-
			1,797.10	1,207.35
	<u>LABOUR</u>			
	TO REPLACE SIDE MIRROR RH ,ETC REPAIR FRT DOOR RH ,FRT FENDER RH ,FRT BUMPER .INCLUSIVE OF THE REPAIR OF MIRROR COVER RH XF R.		3,000.00	500.00
	TO SPRAY FRT DOOR RH ,SIDE MIR COVER RH ,FRT FENDER RH ,FRT BUMPER .		4,000.00	400.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
			7,621.00	1,521.00
GRAND TOTAL			9,418.10	2,728.35
RECOMMENDED COST OF REPAIRS				2,728.35

Report Ref No. CC4/FCI21007684/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKM 991R

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKM 991R

RE-INSPECTION

