

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007692/AVCN2**Date:** 31/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00008192100

**Claimant Vehicle No :** SLU868K **Insured Vehicle No :** SKF7215P

Date of Loss: 13/07/2021 Nature of Claim: TP Claim No: SNM21D203924/C03/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLU868K**

Make & Model: BMW 320I, 2.0 (A) Engine No: B557I317N46B20BD

Reg. Date: 25/06/2009 (Man. Year: 2009) Chassis No: WBAWA52020P300662

Colour: White Odometer: 183471 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,066.00	4,020.80	1,045.20	20.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	580.00	650.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,296.00</b>	<b>4,600.80</b>	<b>1,695.20</b>	<b>26.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,296.00</b>	<b>3,600.00</b>	<b>2,696.00</b>	<b>42.82</b>

**INSPECTION**

Date of Assignment: 15/07/2021

Date Inspected: 19/07/2021 Inspected At: Jec Auto Centre (HQ)  
1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2021)
<b>Parts:</b>	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU868K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,455.00 F	*1,455.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	O/s Necessary	176.00 F	*88.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	645.00 F	*645.00 FL
4	1		*FRONT BUMPER NOZZLE COVER RH	Missing	38.00 F	*38.00 FL
5	1		*FRONT BUMPER NOZZLE PUMP RH	Cracked	148.00 F	*148.00 FL
6	1		*FRONT BUMPER SIDE GRILLE RH	Not Necessary	121.00 F	*- FL
7	1		*HEADLAMP RH	Cracked	1,980.00 F	*1,980.00 FL
8	1		*HEADLAMP LOWER BRACKET RH	Cracked	58.00 F	*58.00 FL
9	1		*HEADLAMP CONTROL UNIT	Not Necessary	345.00 F	*- FL
10	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
11	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,066.00</b>	<b>4,462.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	441.20
<b>Total Parts (\$)</b>	<b>5,066.00</b>	<b>4,020.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	500.00	300.00
2	SPRAY PAINTING	New	500.00	250.00
3	WIRING	New	50.00	30.00
4	TO PERFORM DIAGNOSTIC TEST	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,230.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >