

SLU868K. 2009 June

TP China.
vecon.

BMW 320i Coupe 1995cc

WBAWA52020P300662

Front Number Plate.	MP m	50(SN)	X
Front Bumper	Behind	1455	✓
Front Bumper Clips	MP	50(SN)	✓
Front Bumper Side Holder x02.	RH MP	88	88
		$88 \times 2 = 176$	
Front Bumper Reinforcement.	Dented	645	✓
Front Bumper Nozzle Cover	Missy RH	38	✓
Front Bumper Nozzle Pump.	could RH.	148	✓
Front Bumper Side Grille RH.	MP m	121	X
Headlamp RH	could	1980	✓
Headlamp Lower Bracket RH.	could	58	✓
Headlamp Control Unit.	MP m	345	X

SLU868K.

Panel Beating

Spray Painting.

Wiring.

To perform diagnostic test

~~500~~ 300

~~500~~ 250

~~50~~ 30.

180 X.

6296.00

Wist: 4412

Wm 10%: 3970.80

S.N: 50

Labour: 580

Wbel: 4600.80

L/S: 3.6k
03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: