

ASS. REC. BY: marcus

REF:

CS/SM02100.7696/Uqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD5617Mat Workshop m/s sin huan

of _____

Insured: _____

Policy No. _____

Claims No. CMTD2102091/IJH

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$58K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LTA # 27781

Vehicle: IN / OUT

Date / Time Action / Instruction Rep 7500Veh No: SMD5617M Yr Regn: 27/8/18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: NISSAN Note c.c. 1198Colour: pink A/C: Insured / Std / NI / NASp.Reading: 25522 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1TAE1220982070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or continued

Front

Rear

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 13/7/14 D.O.I. 16/7/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 22/07 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS \$☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)Report Format: TPLump Sum + B: (\$ 4600)

TOTAL

27/7/14 4/5 @ 4600 continued with MR 60H (Red \$3772.85, 45%)

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

LIM WAN CHIN MARIA

DATE	15/7/2021
VEHICLE NO:	SMD 5617 M
MAKE:	NISSAN
MODEL:	NOTE

not Arthur
4/5 # 4600
5 days
Whipshw after you
HP 9009 6608
16/7/21
not

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BOOTLID <i>225.00</i>		1,085.02
2 PCS	BOOTLID DAMPER <i>1018.20</i>		195.00
1 PC	REAR BOOTLID INNER TRIM <i>AMX</i>		162.54
1 PC	REAR BUMPER <i>460.00</i>		480.41
1 PC	REAR BUMPER SPONGE <i>125.00</i>		135.71
1 PC	END PANEL <i>552.80</i>		593.00
1 PC	END PANEL TOP GARNISH <i>70</i>		88.45
1 PC	WEATHER STRIP <i>70</i>		98.72
1 PC	BOOTLID LOCK <i>20/70</i>		178.44
1 PC	REAR FENDER INNER TRIM L/H <i>396.40</i>		464.58
1 PC	WINDSCREEN RUBBER <i>70</i>		95.22
1 PC	NOTE LOGO <i>62.00</i>		79.90
1 PC	CENTER LOGO <i>64.90</i>		65.00
1 PC	LOCK SENSOR <i>one</i>		86.22
1 PC	TAILLAMP L/H <i>one</i>		455.51
----- SUBTOTAL			4,458.72
LESS 10%	----- LESS 10%	-10.00%	-445.87
1 SET <i>Rear</i>	NUMBER PLATE AND HOLDER <i>sent</i>	90.00	90.00
10 PCS <i>Rear</i>	BUMPER CLIP <i>rec</i>	40.00	40.00
1 SET	REVERSE SENSOR <i>shld</i>	280.00	280.00
-	TO INSTALL AND CALIBRATE REVERSE SENSOR	60.00	60.00
-	TO REMOVE AND REFLEX REAR WINDSCREEN TO FACILITATE REPAIR	180.00	180.00
-	TO SUPPLY WINDSCREEN SEALANT	90.00	90.00
-	TO TRANSFER BOOTLID MECHANISMS AND FITTINGS TO NEW BOOTLID	150.00	150.00
-	TO REMOVE AND REFLEX SEAT, INNER TRIMS, FITTINGS AND BOARDS TO FACILITATE REPAIR WORK	350.00	350.00
-	TO REPLACE END PANEL INCLUDE KNOCKING, CUTTING AND WELDING TO REPLACE, INSTALL AND ALIGN ABOVE ITEMS TO SYMMETRICAL SPEC.	1,400.00	1,400.00
-	TO SPRAY PAINT REAR BOOTLID, BUMPER, END PANEL AND FLOORBOARD	1,200.00	1,200.00
-	TO SUPPLY FITTINGS AND INSTALL REVERSE CAMERA.	180.00	180.00

Tel: 6745 5783 Fax: 6744 9582

Email: sinhwemotor@gmail.com

Website: www.sinhwemotor.com

P-366115
10%
P-3295.93
S.V- 320

TOTAL

L-2190
5805.93
202
4644

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

LIM WAN CHIN MARIA

DATE	15/7/2021
VEHICLE NO:	SMD 5617 M
MAKE:	NISSAN
MODEL:	NOTE

QUANTITY	DESCRIPTION	UNIT	AMOUNT
-	TO SUPPLY AND TUFF KOTE	60	220.00 220.00
-	TO CARRY OUT WIRE CHECKING	20	120.00 120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 6745 5783 Fax: 6744 9582
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

TOTAL \$8,372.85