

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007697/DUCE2

Date: 25/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00065232000
Claimant Vehicle No: JQG2971 Insured Vehicle No: GBF2654U
Date of Loss: 07/07/2021 Nature of Claim: TP Claim No: SNM21D203925/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JQG2971**
Make & Model: YAMAHA LC135, 134cc Engine No: G3A1E215249
Reg. Date: 24/07/2014 (Man. Year: 2014) Chassis No: PMYUG0310E0215249
Colour: Multi-colour Odometer: 0 km
Engine Capacity: 135 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 90/80 R17
Front Left Side: Pirelli 2 mm Rear Left Side: Pirelli 2 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,348.30	1,817.30	1,531.00	45.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	570.00	170.00	400.00	70.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,918.30	1,987.30	1,931.00	49.28
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,918.30	1,500.00	2,418.30	61.72

INSPECTION

Date of Assignment: 21/07/2021
Date Inspected: 16/07/2021 Inspected At: Sg 98 Motor Pte Ltd (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
#01-21
Singapore 569622
Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Nov 2021)	
Parts:	N/A	YAMAHA LC135 134cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JQG2971)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET RIM	Repair	280.00 FL	*- FL
2	1		*BOX RACK	Bent	135.00 FL	*135.00 FL
3	1		*TAIL LAMP	Broken	155.00 FL	*155.00 FL
4	1		*PILLION FOOTREST BRACKET O/S	Broken	120.00 FL	*120.00 FL
5	1		*REAR MUDGUARD	Cracked / Broken	185.00 FL	*185.00 FL
6	2		*REAR TAIL SIDE PANEL	Broken	125.00 FL	*125.00 FL
7	1		*HANDLE BAR	Not Necessary	125.00 FL	*- FL
8	1		*CLUTCH LEVER	Not Necessary	76.00 FL	*- FL
9	1		*SET MIRROR	O/S Broken	78.00 FL	*39.00 FL
10	1		*FRONT LH SIDE PANEL	Not Necessary	135.00 FL	*- FL
11	1		*FRONT CENTRE PANEL	Cut	145.00 FL	*145.00 FL
12	1		*FRONT MUDGUARD	Cut	185.00 FL	*185.00 FL
13	1		*HEAD LAMP COVER - TOP	Not Necessary	155.00 FL	*- FL
14	1		*FRONT SIGNAL RH	Scratched	65.00 FL	*65.00 FL
15	1		*FRONT RH SIDE PANEL	Cut	85.00 FL	*85.00 FL
16	1		*BRAKE LEVER	Cut	68.00 FL	*68.00 FL
17	1		*INNER PANEL GARNISH	Cut	125.00 FL	*125.00 FL
18	1		*FOOTREST O/S	Bent	65.00 FL	*65.00 FL
19	1		*FOOTREST RUBBER O/S	Deformed	55.00 FL	*55.00 FL
20	1		*SET FORK TUBE	Not Necessary	480.00 FL	*- FL
21	1		*EXHAUST GUARD	Cut	195.00 FL	*195.00 FL
22	1		*REAR BOX	Dislodged	320.00 FS	*150.00 FS
23	1		*REAR NUMBER PLATE	Bent	15.00 FS	*15.00 FS
24	1		*BODY DECAL STICKER	Necessary	110.00 FS	*80.00 FS
25	1		*IU UNIT	Not Necessary	170.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,652.00	1,992.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	303.70	174.70
Total Parts (\$\$)	3,348.30	1,817.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	250.00	150.00
3	REPLACE REAR RIM, FORK TUBE, FORK OIL SEAL	New	80.00	20.00
4	ALIGN REAR FRAME BODY	New	200.00	0.00
			Gross Labour Cost (\$\$)	170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >