

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
SMRT AUTOMOTIVE SERVICES PTE LTD			Ref:	CS/SMR21007698/Uuf3n2	
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	27/07/2021	
			Code:	SMR	
1. Policy Particulars :- THIRD PARTY CLAIM					
Insured Veh.	SMB 1459P	Veh. Inspected		SKW 3035D	
Policy No.		Coverage (\$)		0.00	
Claim No.	BUS/07/21/5023	Excess (\$)		0.00	
Assign From	HUA YEN	Assign Date		15/07/2021	
2. Vehicle Particulars & Condition					
Make & Model	TOYOTA WISH (A)	c.c		1798	
Engine No.	HIDDEN	Year of Reg.		2015	
Chassis No.	JTDGG20W30J002698	Colour		ORANGE	
Odometer	142999 KM	Steering		IN ORDER	
Brakes	IN ORDER	Modification		SPORTS RIM	
General	FAIR				
3. Conditions of Tyres					
	Size	Make		Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA		6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA		6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA		6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA		6 mm	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
DAMAGES SEE DETAILS.					
5.	General Information				
Accident Date	14/07/2021	Inspection Dat	е	16/07/2021	
Survey held at	FASTECH AUTO PTE LTD				
	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORM	MAL PERIOD FOR REPAIR:		10 Worl	king Days	
5. Accident Date Survey held at 5a. A)THE INSPECTIO B)IN ACCORDANC 5b.	DAMAGES SEE DETAILS. General Information Accident Date 14/07/2021 Inspection Date 16/07/2021 Survey held at FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				