

ASS. REC. BY: Marcus

REF:

CS/SMR21007698/Uuf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKW 30350

at Workshop m/s

ff

of

Insured:

SM B 1459P

Policy No.

Claims No.

BUS/07/21/5023

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$58k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

265f.

Veh No: SKW 30350

Yr Regn:

26/10/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Toyota wish

c.c

1798

Colour:

grey

A/C: Insured / Std / NI / NA

Sp. Reading

142999

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDG620W30J002698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R 15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/7/21

D.O.I.

16/7/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S - Rear R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 11K.

have G.A LTA \$4230
net 8 14970

26/7/2021 Revise IA to Jimmy via email

23/7/21 1/3 \$14,900 confirmed with ACen 10 repair days

(RED \$29875.40; 67%)

Date/Time, File Pass to?

☐

Preli. Report

1) 26/7 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TP

Lump Sum / +B (\$14900

)

TOTAL

Submit to insurance

Not Authorised
10/1/21
1/5 @ 14.900
10 days.

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE No : SKW 3035D

1PC	REAR FENDER O/S	body DO	821.60	\$1,299.10	✓
1PC	REAR FENDER GLASS O/S	11		\$680.00	X
1PC	REAR FENDER UNDER SHIELD O/S	11		\$211.20	X
1PC	REAR FENDER INNER TRIM BOARD O/S	2/cane	481.00	\$688.50	✓
1PC	REAR WHEEL HOUSING PANEL O/S	R		\$1,099.10	X
1PC	REAR AIR VENT O/S	11		\$66.20	X
1PC	TAILLAMP O/S	Cne	391.00	\$485.20	✓
1PC	TAILGATE	R		\$1,448.90	X
1PC	TAILGATE REFLECTOR O/S	Cne	295.10	\$355.20	✓
1PC	REAR BUMPER	D.S		\$585.20	✓
1PC	REAR BUMPER REFLECTOR O/S	11		\$55.30	X
1PC	REAR BUMPER SIDE HOLDER O/S	Cne		\$66.50	✓
1SET	REAR BUMPER CLIPS	nee		\$50.00	✓
1PC	REAR EXHAUST	DO		\$1,087.20	✓
1PC	REAR EXHAUST HEAT SHIELD	D.S		\$135.40	✓
1PC	REAR EXHAUST MOUNTING	Torn		\$45.00	✓
1PC	REAR FLOOR PANEL	R		\$1,410.10	X
1PC	REAR FLOOR SIDE O/S PANEL	body DO		\$244.10	✓
1PC	REAR DOOR O/S	body DO	1511.79	\$1,629.20	✓
1PC	REAR DOOR INNER LOCK O/S	sketch	388.50	\$399.50	✓
1PC	REAR DOOR INNER RUBBER O/S	11		\$288.90	X
1PC	REAR DOOR INNER TRIM BOARD O/S	11		\$681.10	X
1SET	REAR DOOR FRAME BLACK STICKER O/S	nee		\$150.00	✓
1PC	ROCKER PANEL O/S	R		\$850.10	X
1PC	ROCKER PANEL GARNISH O/S	D.S/wrapped	805.10	\$845.20	✓
1SET	ROCKER PANEL GARNISH CLIPS/S	nee		\$50.00	✓
1PC	REAR AXLE BEAM	3/cane	2400.20	\$2,800.20	✓
1PC	REAR AXLE BEAM BUSH	11		\$202.50	X
1PC	REAR WHEEL HUB BEARING O/S	Damaged	650.50	\$681.00	✓
1PC	REAR SHOCK ABSORBER O/S	Bush	222.10	\$291.20	✓
1PC	ROOF LINING	Torn	2500.00	\$2,959.10	✓
1PC	CURTAIN AIR BAG O/S	Actual	2800.00	\$3,980.10	✓
1PC	DRIVER AIR BAG	Actual	2650.00	\$2,998.20	✓
1PC	DRIVER SPIRAL SENSOR	Actual		\$245.00	✓
1PC	PASSENGER AIR BAG	Actual	3650.00	\$3,990.20	✓
1PC	DASHBOARD	Bus		\$921.75	✓
1PC	PASSENGER SEAT BELT	Actual	950	\$1,280.00	✓
1PC	DRIVER SEAT BELT	Actual	950	\$1,280.00	✓
1PC	AIR BAG CONTROL UNIT	Actual		\$1,250.00	✓
				\$37,785.40	

252

S.NETT

1PC	REAR SPORT RIM O/S	CNE	\$680.00	500	5/20
1PC	REAR TYRE O/S	put	\$200.00	60%	20
1PC	REAR FENDER GLASS SEALANT O/S	all	\$50.00	40	
TO CHECK WIRING			\$50.00	-20	
TO DISMANTLE & REFIX REAR REVERSE SENSOR			\$80.00	-50	
TO DISMANTLE & REFIX REAR FENDER GLASS O/S			\$100.00	✓	
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$100.00	✓	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE			\$380.00	250	
TO CONDUCT WHEEL ALIGNMENT			\$120.00	60	
TO DISMANTLE & REFIX REAR DOOR MECHANISM			\$100.00	60	
TO DISMENTLE & REPLACED ROOF LINING			\$280.00	180	
TO DISMANTLE & REPLACED DASHBOARD			\$300.00	250	
TO DISMANTLE & REPLACED AIR BAG			\$300.00	✓	
TO RESET & REPROGRAMME AIR BAG SYSTEM			\$300.00	200	
TO SPRAY RUST PROOFING			\$150.00	60	
LABOUR FOR PANEL BEATING & REPLACED PARYS			\$2,000.00	1200	
TO PUTTY & SPRAY PAINTIG			\$1,800.00	1400	
TOTAL			\$44,775.40		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2629724

252

9-19777-93

S.N-660

L-4230

24687-93