



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO21003032/Utf3e2-1 Date: 02/08/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 3239Z	Veh. Inspected	SJZ 233P
Policy No.	D20MTPV01008884	Coverage (\$)	0.00
Claim No.	CMTD2100698/LOR	Excess (\$)	0.00
Assign From	HWANG SHIANG YI	Assign Date	15/07/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050402R159842	Colour	GREY
Odometer	80380 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/03/2021	Inspection Date	08/03/2021
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	