



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO21004452/Utf3e2-1	
			Date: 27/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9269C	Veh. Inspected	YP 9994S	
Policy No.	D20MTHCVE000800	Coverage (\$)	0.00	
Claim No.	CMTD2101076/GPL	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	16/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi fuso FK62 (A)	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	FK62FMA40050	Colour	WHITE	
Odometer	133689 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/70 R19.5	FALKEN	6 mm	
L/H Front Tyre	245/70 R19.5	FALKEN	6 mm	
R/H Rear Tyre	245/70 R19.5 (D)	FALKEN	6/6 mm	
L/H Rear Tyre	245/70 R19.5 (D)	FALKEN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2021	Inspection Date	04/05/2021	
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	