

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21007708/KTCE2

**Date:** 01/10/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00084832000  
**Claimant Vehicle No :** SGW3642Z **Insured Vehicle No :** GBK5716D  
Date of Loss: 14/07/2021 Nature of Claim: TP Claim No: SNM21D203936/C02/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW3642Z**  
Make & Model: HONDA CIVIC, 1.8 (A) Engine No: R18A12033443  
Reg. Date: 14/07/2007 (Man. Year: 2007) Chassis No: JHMFD16307S215644  
Colour: White Odometer: 188151 km  
Engine Capacity: 1799 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: KAPSEN 8 mm Rear Left Side: Michelin 5 mm  
Front Right Side: KAPSEN 8 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,163.00	2,060.00	1,103.00	34.87
Miscellaneous Items	107.60	95.00	12.60	11.71
Labour	407.40	386.40	21.00	5.15
Paintwork Labour	721.17	721.17	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,399.17</b>	<b>3,262.57</b>	<b>1,136.60</b>	<b>25.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	4,399.17	2,600.00	1,799.17	40.90
<b>+ GST 7.00/7.00% (S\$)</b>	307.94	182.00	125.94	40.90
<b>Nett Amount (S\$)</b>	<b>4,707.11</b>	<b>2,782.00</b>	<b>1,925.11</b>	<b>40.90</b>

### INSPECTION

Date of Assignment: 19/07/2021 Present Location: S & H Motor Pte Ltd (Sin Ming)  
Date Inspected: 16/07/2021 Inspected At: S & H Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #07-02, Sin Ming AutoCity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW3642Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		3,163.00 F	*2,060.00 F
Total Parts (S\$)						2,060.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	107.60	95.00
Sub Total (\$\$)			107.60	95.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	721.17	721.17
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	407.40	386.40
Gross Labour Cost (\$\$)			1,128.57	1,107.57

Report was unsubmitted during this print-out.

< END OF ESTIMATES >