



# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Company Reg No: 200704370C GST Reg No : 200704370C

16/7/2021

Name of Insurance Company: India International Insurance Pte Ltd

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLG9847K

NO	QTY	DESCRIPTION	LIST PRICE
1	1 PC	REAR LH DOOR <i>3ad507</i>	\$ 960.60 ✓
2	1 PC	REAR LH BLACK TRIM MOULDING <i>215</i>	\$ 47.80 ✓
3	1 PC	REAR LH FENDER <i>DD</i>	\$ 1,063.00 ✓
4	1 PC	REAR BUMPER <i>R</i>	\$ 828.60 X
5	1 PC	REAR BUMPER CLIPS <i>11cc</i>	\$ 40.00 ✓
6	1 PC	REAR BUMPER SIDE <i>DLS</i>	\$ 132.60 ✓
			\$ 3,072.60
		less 20%	\$ (614.52)
			\$ 2,458.08
<b>SPECIAL NETT ITEM :</b>			
7		TUFF COAT	\$ 100.00 <i>60</i>
8		TO REMOVE AND RENEW REAR PARTS	\$ 880.00 <i>600</i>
9		WIRING CHECK (REAR )	\$ 30.00 <i>20</i>
10		SPRAY PAINTING (REAR )	\$ 680.00 <i>600</i>
			\$ <u>4,148.08</u>

*not about  
rbr  
H/S \$2150/  
4 days  
21/7/21  
take photo after repair*

*C04646-T7A-30022*

*P-18107  
20%  
1448.58  
1280  
2728.58  
20%  
2182.86*

*Ulu Jasper*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: