



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21007711/Evf3e2	
			Date: 31/08/2021	
			Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YP 889Y
	Policy No.	D-21096813MFCV/17	Coverage (\$)	0.00
	Claim No.	D21002065MFCV	Excess (\$)	750.00
	Assign From	ERIC WOO	Assign Date	16/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ SPRINTER	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDB9066532P181271	Colour	WHITE
	Odometer	244655 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/75 R16C	YOKOHAMA	4 mm
	L/H Front Tyre	195/75 R16C	YOKOHAMA	4 mm
	R/H Rear Tyre	195/75 R16C	YOKOHAMA	4 mm
	L/H Rear Tyre	195/75 R16C	YOKOHAMA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/07/2021	Inspection Date	19/07/2021
	Survey held at	209 PANDAN GARDENS		
	Repairer	CYCLE & CARRIAGE INDUSTRIES PL		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$55,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	