



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111 X

ESTIMATE FOR YP889Y

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 49181
Reg No/Reg Date YP889Y / 07/01/2016
Date In/Mileage / 243898
Chassis No WDB9066532P181271
Engine No 65195532993520
Make/Model MBCV/516CDI/3665 Spr
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	16/07/2021/ 09:51	PC	610 / Philip Cheong
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

- A 00940101 TO REMOVE & REPAIR SIDE PANEL FRONT DOOR RH 462 x 3
A 00940101 TO REMOVE & REFIT INNER BOX SHELF (photo)
A 00940101 LOGO
A 00940101 TO PUTTY & SPRAY PAINTING SIDE PANEL FRONT 462 x 3
DOOR AND LOWER SHIRT
M SIDEWALL FRAME 1.00
M PANELING (new dss) 1.00
M MOULDING (h n) 1.00

2700.00
1800.00
2250.00
1920.00
1512.33
469.61
244.97

ESTIMATE

Store (LKK) 00-AL AL
19/7/21, 3-88m EXCESS-?
83228813 P/P
My B/L sy
7 dys

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation

Confirmed & accepted by survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 10,926.91
7% GST on 10926.91 764.88
Total Payable 11,691.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714389
Fax: (65) 67756310
www.mercedes-benz.com.sg



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany