



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR YP889Y

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **49181**
Reg No/Reg Date **YP889Y / 07/01/2016**
Date In/Mileage **/ - 243898**
Chassis No **WDB9066532P181271**
Engine No **65195532993520**
Make/Model **MBCV/516CDI/3665 Spr**
Colour/Trim **914 Arctic White / NA NOT APPLICABLE**

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	23/08/2021/ 13:48	PC	610 / Philip Cheong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 00940101								2700.00
TO REMOVE & REPAIR SIDE PANEL ,FRONT DOOR RH								
A 00940101								1800.00
TO REMOVE & REFIT INNER BOX SHELF								
A 00940101							0.05	800.00
LOGO								
A 00940101								1920.00
TO PUTTY & SPRAY PAINTING SIDE PANEL ,FRONT								
DOOR AND LOWER SHIRT								
X SIDEWALL FRAME					1.00	1512.33	00.00	1512.33
X PANELING					1.00	469.61	00.00	469.61
X MOULDING					1.00	244.97	00.00	244.97
X PROTECTIVE STRIP					1.00	67.19	00.00	67.19
X MARKER LAMP					1.00	48.72	00.00	48.72

Confirmed & accepted by

7% GST on **9562.82** **Nett 9,562.82**
669.40
Total Payable 10,232.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714389
Fax: (65) 67756310
www.mercedes-benz.com.sg