

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 23 Jul 2021

Preliminary Advice

Insured : SMS5987R
Vehicle No
TP Vehicle No : FBS6585R
Accident Date : 09/07/2021
Make : HONDA CBR150R
Assignment Date : 16/07/2021
Date of Inspection : 22/07/2021
Est. Duration of Repair : 2
Inspection At : EVERBRIGHT MOTOR CYCLES CO (HQ)
53 PAYA UBI INDUSTRIAL PARK, #01-10/12 UBI AVENUE 1
SINGAPORE 408934

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,173.80
Revised Amount	:S\$	957.60
Check Items (Estimated)	:S\$	44.82
Total	:S\$	1,002.42

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

() Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.