

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA2246U

MAKE HYUNDAI

MODEL I-40

DATE 15/07/21

MVA CHIANG/ AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				<i>Rp</i> \$2,171.40
1	REAR FENDER LH			<i>x</i> \$35.60
1	REAR BUMPER SIDE BRACKET LH			<i>cut</i> \$217.20
1	REAR WHEEL CAP LH			<i>Rp</i> \$2,201.10
1	REAR DOOR PANEL			<i>bt</i> \$2,256.40
1	FRONT DOOR PANEL			\$6,881.70
	SUB TOTAL			\$1,376.34
	20.00%			\$5,505.36
	DISCOUNTED TOTAL			
1	FRONT DOOR ADVERTISEMENT			<i>cut</i> \$100.00
1	REAR DOOR ADVERTISEMENT			<i>cut</i> \$100.00
1	REAR FENDER ADVERTISEMENT			<i>cut</i> \$100.00
1	FRONT DOOR COMFORT & TEL NUMBER			<i>net</i> \$75.00
1	REAR DOOR COMFORT APP STICKER			<i>net</i> \$80.00
				\$455.00
	Labour Charge			
	Panel Beating			<i>560</i> \$850.00
	Spray Painting Charge			<i>1000</i> \$1,100.00
	Remove/refix door parts to new door			<i>80</i> \$120.00
	Remove/refix rear upholstery			<i>x</i> \$90.00
	Tuff coat			<i>30</i> \$90.00
	TOTAL LABOUR			\$2,250.00
	ESTIMATE TOTAL			\$8,210.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfer 97495749
 WP 16/7/21 215pm
 1/3 Rising after repair
 Tanfer e (Khan) on
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 16.07.2021 09:07

Page : 1

JOB CARD

Sales Order: 4099182

JC NO.: 305478534

Team: ARC Repair TP(CLSO)1

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
iESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO.: SHA2246U	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 15.07.2021 08:55
YR OF MANU. 13.12.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098613	COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 14.07.2021
NATURE: 3P 14.07.2021

S/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

e No.:

SHA2246U

CHIANG

Exit Pass

Vehicle No.:

SHA2246U

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard