

# MFORTDELGRO ENGINEERING PTE LTD

## FAIR ESTIMATE\*

VEHICLE NO SHA2246U  
MAKE HYUNDAI  
MODEL I-40

DATE 15/07/21  
MVA CHIANG/ AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR FENDER LH		Rx	\$2,171.40
1	REAR BUMPER SIDE BRACKET LH		nn x	\$35.60
1	REAR WHEEL CAP LH		aut	\$217.20
1	REAR DOOR PANEL		Rx	\$2,201.10
1	FRONT DOOR PANEL		bt	\$2,256.40
	<b>SUB TOTAL</b>			<b>\$6,881.70</b>
	<b>20.00%</b>		2473.60	<b>\$1,376.34</b>
	<b>DISCOUNTED TOTAL</b>		1978.88	<b>\$5,505.36</b>
1	FRONT DOOR ADVERTISEMENT		aut	\$100.00
1	REAR DOOR ADVERTISEMENT		aut	\$100.00
1	REAR FENDER ADVERTISEMENT		aut	\$100.00
1	FRONT DOOR COMFORT & TEL NUMBER		wp	\$75.00
1	REAR DOOR COMFORT APP STICKER		wp	\$80.00
	<b>Labour Charge</b>		455	<b>\$455.00</b>
	Panel Beating		560	\$850.00
	Spray Painting Charge		1000	\$1,100.00
	Remove/refix door parts to new door		60	\$120.00
	Remove/refix rear upholstery		nn x	\$90.00
	Tuff coat		30	\$90.00
	<b>TOTAL LABOUR</b>		1650	<b>\$2,250.00</b>
	<b>ESTIMATE TOTAL</b>		4083.88	<b>\$8,210.36</b>
			1/58 3250	
			# 3 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfer 9779 5749  
WP 16/7/21 @ 2:15pm  
1/58 Resurvey after repair  
Tanfer C (Khando) on  
# 3 days

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: