

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Qty Date Particulars

REPAIR PERFORMA INVOICE

Vehicle number FBQ1880G
 Make / Model YAMAHA JUPITER
 Chassis number MH3UE1120KJ228606
 Accident date 9/7/21
 Reference KK2107-18

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT FAIRING (BLUE) / Cut	300.00
2	FRONT FAIRING INNER (LH/RH) 8 / cut	500.00
2	FRONT FAIRING LOWER (LH/RH) X na	500.00
1	FRONT HEADLAMP / Cut	350.00
1	FRONT HEADLAMP FAIRING (BLUE) / Cut	280.00
1	FRONT HEADLAMP FAIRING (BLACK) / Cut	250.00
2	FRONT FORK 8 Repair	550.00
1	FRONT FORK BRACKET 8 / BT	180.00
1	HANDLE BAR / BT	250.00
1	BRAKE LEVER / Cut	90.00
1	BRAKE LEVER BRACKET X	90.00
1	BRAKE PEDAL X	90.00
1	FOOTREST / Cut	90.00
1	FOOTREST RUBBER / Cut	90.00
1	FOOTREST BRACKET X na	110.00
1	PILLION FOOTREST / Cut	90.00
1 SET	BALANCER /	85.00
1 SET	WING MIRROR /	150.00
1	REAR FAIRING LH / Cut	400.00
1	FRONT FENDER /	250.00
Signal lamp RH - BR.		4695.00
Less 10 %		469.50
Subtotal		4225.50
Balance C/F		4225.50
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	FRONT NUMBER PLATE / Cut	50.00 15
1	IU / Cut	156.00
1	GEAR SHAFT OIL X na	24.00
1	FORK OIL SEAL 8 = 3 mec.	120.00
1	FORK OIL	60.00
Subtotal		410.00
Balance C/F		4635.50
LABOUR AND MISCELLANEOUS CHARGES		
1	TO CHECK WIRING SYSTEM	60.00
2	TO REMOVE & REFIT EXHAUST SILENCER	200.00 150
3	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00
4	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	600.00 300
Subtotal		1260.00
Grand total		5895.50

3 Days
 Upside Repair
 After repair photos. 16/7/21