



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007721/Kvf3n2 Date: 10/08/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SMG 9825L	<b>Veh. Inspected</b>	SLT 7740D	
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	C10010931/JM	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	16/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA C-HR (A)	<b>c.c</b>	1797	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017	
<b>Chassis No.</b>	ZYX102071675	<b>Colour</b>	METALLIC GREY	
<b>Odometer</b>	377498 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	215/60 R17	CONTINENTAL	6 mm	
<b>L/H Front Tyre</b>	215/60 R17	CONTINENTAL	6 mm	
<b>R/H Rear Tyre</b>	215/60 R17	NEXEN	9 mm	
<b>L/H Rear Tyre</b>	215/60 R17	NEXEN	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	13/07/2021	<b>Inspection Date</b>	22/07/2021	
<b>Survey held at</b>	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>			<b>3 Working Days</b>	