

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64815131

H L Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLT 7740 D
Make : Toyota C-HR
Year : 2017

*Not Withheld
C/Ly 8 2900h
Arriving After Rain
3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s door outer protector	<i>CM</i>	\$405.10	<i>✓</i>
1 pc	Rear o/s door protector	<i>nd/ha</i>	\$385.70	<i>✓</i>
1 pc	Rear o/s fender arch garnish	<i>nd</i>	\$187.50	<i>✓</i>
			\$978.30	
		Less 25 %	\$244.58	
			\$733.72	

S Nett

1 set	O/S rocker panel step garnish	<i>PM 1900</i>	<i>CM</i>	\$2,600.00	<i>✓</i>
30 pcs	Fender arch and rocker panel garnish clip	<i>nd</i>	\$2.00	\$60.00	<i>✓</i>
				\$2,660.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$500.00	<i>2001</i>
To putty & spray paint on accident affected portion.	\$1,000.00	<i>6001</i>
To spray anti rust on accident affected portion.	\$120.00	<i>nd X</i>
Remove/renew o/s rocker panel step garnish.	\$200.00	<i>1501</i>
Total	\$5,213.72	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: