

Attn Kenneth
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLP4929T
 TP/SMRT

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

TEL: 64823888
 ATTN: Motor Claim Department

FAX: 63687421

WS Ref: TP/SMRT
 Claim Type: Third Party
 Accident Date: 11/07/2021
 TP Veh Reg No: SHD6277M

Not Authored

Primary Repair

3 days

Estimate No: ES2190688/YISHUN
Date: 21 Jul 2021
Policy No: 5122116353
Veh Reg No: SLP4929T
Make/Model: HONDA HONDA HIT 1.3GF CVT
Chassis No: GK31343822
Engine No: L13B1452135
Reg. Date: 21/03/2019

Estimate Repair Cost to Vehicle No :SLP4929T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	821.20	1 PC	821.20	✓
2 FRONT BUMPER LH SIDE RETAINER	12.00	1 PC	12.00	✓
3 FRONT BUMPER LH FOG LAMP GARNISH	173.10	1 PC	173.10	✓ SVC
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
			1,027.30	
		Less 20%	205.46	821.84
Special Net				
5 FRONT NUMBER PLATE	30.00	1 PC	30.00	✓
			30.00	30.00
Labour				
6 REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	400.00	1 LA	400.00	3001
7 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER INNER PANEL,FRT RH FENDER	450.00	1 LA	450.00	4001
8 TO APPLY,REMOVE & REFIX OPC SEAL AND SEND VEHICLE FOR INSPECTION (INCLUDING EDAY LICENCE)	80.00	1 LA	80.00	✓
			930.00	930.00
			Total	S\$ 1,781.84
			Add GST @ 7%	124.73
			Total Amount Payable	S\$ 1,906.57

Parti \$854.20
20% 170.84

683.36
30
780

\$1493.36

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE