

Our Ref : WH0752					
Vehicle No. : SJP4601L				Page No. 1	
Make & Model : TOYOTA WISH 1.8 AUTO					
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)		SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>				
1	Front door RH ✓ DO			1719.00	
1	Front door upper hinge X			231.00	
1	Front door lower hinge X			231.00	
1	Front door lock RH ✓			790.00	
		Part Items Total:	-25%	2971.00	
				-742.75	
				2228.25	
	<u>SPECIAL NETT ITEMS</u>				
1	Front Door rubber seal RH ✓ CPU			100.00	
SN Items Total:				100.00	
Total Parts:				2328.25	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0752
Vehicle No. : SJP4601L
Make & Model : TOYOTA WISH 1.8 AUTO

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To perform anti-rust treatment on affected areas	30.00	/
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
5	To remove and refix/replace Front door RH fitting, trimmings, garnish, window glass and mechanism.	100.00	30
Labour Total :		990.00	
TOTAL (PARTS & LABOUR):		3318.25	

Steve CLKK)
21/7/21, 12:30L

WHL RL
L/R
My AL by
3 4 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: