



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

LKK Auto Components hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATE

Account Details			Account No.		Signature:		Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Date:		Mdm Tan Suat Kiau 39 Elias Terrace Singapore 519792 Mobile: 91396309	
			Document No.					
			0					
			Document Date		16/08/2021			

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	16/01/2019	SMH2404J	0	21090	67/DS/SMH2404J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3101161532	2NRX408496	60	Sam San Joi	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ5892H ACC DATE:15/07/2021 DRIVE IN:15/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	720	1080		1800.00
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	590	1180		1770.00
6	1	SPC593-0D007 S1 LED FOG LAMP SET with garnish o/s	1.00	392.40		392.40
7	2	K52119-0U932 COVER, FR BUMPER, L	1.00	500.80	X	500.80
8	3	S52535-0D230 RETAINER, FR BUMPER	1.00	101.60	X	101.60
9	4	S52161-0K040 CLIPS	10.00	4.10	X	41.00
10	5	S53801-0D100 FENDER SUB-ASSY, FR	1.00	770.60	X	770.60

For & on behalf of		Customer's Signature	Charge Summary	Total	
Borneo Motors (Singapore) Pte Ltd				5,708.80	
 Please acknowledge receipt of vehicle		Parts	1,806.40	GST 7.00%	399.62
		Labour	3,902.40		
		Sublet	0.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	6,108.42

not Authorised
all
p/p
Haps. Engrs. Atty
16/8/21
Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mdm Tan Suat Klay 39 Elias Terrace Singapore 519792 Mobile: 91396309		
			Document No. 39012068				
			Document Date 08/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	16/01/2019	SMH2404J	26017	21090	67/DS/SMH2404J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B23F3101161532		2NRX408496	60	Sam San Joi	16/07/2021 9.37		08/09/2021 15.17
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ5892H ACC DATE:15/07/2021 DRIVE IN:15/07/2021 DATE-IN:16/08/2021 DATE SURVEY:16/08/2021 NO OF REPAIR DAYS:4 DAYS BY:MARCUS(LKK)				30.00	
2	B	BP-LAB2 CHECK LIGHTNG & WIRING SYSTEM	*			122.40	
3	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	BP03			1080.00	
4	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	*			1180.00	
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
6	1	SPC593-0D007 S1 LED FOG LAMP SET	1.00	392.40		392.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 2,984.80
Please acknowledge receipt of vehicle			Parts		392.40	GST 7.00%	208.94
			Labour		2,412.40	Less	0.00
			Sublet		180.00		
			Lubrication/Fluid		0.00		
			Others		0.00	Amount Due	3,193.74

Customer Copy