



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mdm Tan Suat Kiau 39 Elias Terrace Singapore 519792 Mobile: 91396309		
			Document No. 0				
			Document Date 16/07/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	16/01/2019	SMH2404J	0	21090	67/DS/SMH2404J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B23F3101161532		2NRX408496	60	Sam San Joi	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ5892H ACC DATE:15/07/2021 DRIVE IN:15/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00	
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS				1800.00	
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS				1770.00	
6	1	SPC593-0D007 S1 LED FOG LAMP SET	1.00	392.40	15.00	333.54	
7	2	K52119-0U932 COVER, FR BUMPER, L	1.00	500.80		500.80	
8	3	S52535-0D230 RETAINER, FR BUMPER	1.00	101.60		101.60	
9	4	S52161-0K040 CLIPS	10.00	4.10		41.00	
10	5	S53801-0D100 FENDER SUB-ASSY, FR	1.00	770.60		770.60	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							5,649.94
			Please acknowledge receipt of vehicle		Parts 1,747.54		GST 7.00% 395.50
					Labour 3,902.40		Less 0.00
					Sublet 0.00		
					Lubrication/Fluid 0.00		
					Others 0.00		Amount Due 6,045.44

Customer Copy