



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

LKK Auto Settlements hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Acknowledged by Repairer

Account Details		Account No.	Customer Details	
India International Insurance P L		S1000006 / ICIII1	Signature:	
64 Cecil Street		Document No.	Date:	
#06-02 IOB Building		0	Mdm Tan Suat Kiau	
Singapore 049711		Document Date	39 Elias Terrace	
Attn: Motor Claims Dept		16/08/2021	Singapore 519792	
			Mobile: 91396309	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	16/01/2019	SMH2404J	0	21090	67/DS/SMH2404J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3101161532	2NRX408496	60	Sam San Joi	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ5892H ACC DATE:15/07/2021 DRIVE IN:15/07/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	720	1080		1800.00
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	530	1180		1770.00
6	1	SPC593-0D007 S1 LED FOG LAMP SET with garnish o/s	1.00	392.40		392.40
7	2	K52119-0U932 COVER, FR BUMPER, L	1.00	500.80	X	500.80
8	3	S52535-0D230 RETAINER, FR BUMPER	1.00	101.60	X	101.60
9	4	S52161-0K040 CLIPS	10.00	4.10	X	41.00
10	5	S53801-0D100 FENDER SUB-ASSY, FR	1.00	770.60	X	770.60

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	5,708.80
Please acknowledge receipt of vehicle		Parts	1,806.40	GST 7.00% Less Amount Due
		Labour	3,902.40	
		Sublet	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			399.62	0.00
			6,108.42	

not attached
p/p
Hays, Complete All repair
16/8/21
Customer Copy