



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200316

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/01/2022
Reference CC3/CTI21007731/T1ea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1822Y
Insured Veh. SKF 7215P
Claim No. SNM21D203924/C04
Policy No. DMPCSNW00008192100
Accident Date 13/07/2021
Inspection Date 10/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21007731/T1ea3q2	
			Date: 14/01/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKF 7215P	Veh. Inspected	SHD 1822Y
	Policy No.	DMPCSNW00008192100	Coverage (\$)	0.00
	Claim No.	SNM21D203924/C04	Excess (\$)	0.00
	Assign From		Assign Date	10/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHC851CVLU212221	Colour	SILVER
	Odometer	95413 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	HANKOOK	6 mm
	L/H Front Tyre	195/65 R15	HANKOOK	6 mm
	R/H Rear Tyre	195/65 R15	HANKOOK	6 mm
	L/H Rear Tyre	195/65 R15	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/07/2021	Inspection Date	10/08/2021
	Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1822Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	430.90	-
1	FRONT BUMPER CENTRE GRILLE COVER -UPPER	TO REPAIR SEE LABOUR	108.50	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	708.90	-
1	FRONT BUMPER EMBLEM 'HYUNDAI'	NOT NECESSARY	28.00	-
1	FRONT BUMPER STRIP	NOT NECESSARY	29.40	-
1	RADIATOR GRILLE	CUT	708.90	708.90
	LESS 20% DISCOUNT		-402.92	-141.78
			1,611.68	567.12
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			148.00	-
	<u>LABOUR</u>			
	TO ADJUST /FOCUS FRONT N/S & O/S HEAD LAMPS .	NOT NECESSARY	80.00	-
	TO CHECK FOR WIRING	NOT NECESSARY	50.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS, INNER TRIMS, CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER CENTRE GRILLE COVER -UPPER .		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT CENTRE GRILLE MOULDING.		400.00	200.00
			1,260.00	400.00
	GRAND TOTAL		3,019.68	967.12



RECOMMENDED COST OF REPAIRS			967.12
-----------------------------	--	--	--------

Report Ref No. CC3/CTI21007731/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1822Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1822Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1822Y

RE-INSPECTION

