

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1822 Y

1 pc	Front bumper	\$	430.90	Ry
1 pc	Front bumper centre grille cover - Upper	\$	108.50	Ry
1 pc	Front bumper centre grille	\$	708.90	Xun
1 pc	Front bumper emblem "HYUNDAI"	\$	28.00	Maxun.
1 pc	Front bumper strip	\$	29.40	Xun.
1 pc	Radiator Grille	\$	708.90	out
		\$	2,014.60	708.90
		\$	402.92	
		\$	1,611.68	567.12
		Less 20%		
S/NETT				
1 pc	Front bumper clips	\$	48.00	X
1 pc	Front number plate with leasing	\$	50.00	X
		\$	50.00	X
		\$	80.00	X
		\$	50.00	X
		\$	180.00	X
			200	
		\$	550.00	
			200	
		\$	400.00	400
		\$	3,019.68	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

567.12
400
\$967.12
2 days #

Tanpin 97495749
WP' 10/8/21 @ 230pm
P/P Requiring new parts
2 days
Tanpin @ 11hauto.com.