

ASSESSMENT FOR REPAIR : FBE5684T**YAMAHA SPARK 135 (55D5)****COE EXPIRY : 06 MAY 2029**

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Handle bar complete ✓ BT	Bent	\$ 120.00	\$ 120.00 ✓
1 pc	Bracket handle ✓ BT	Bent	\$ 80.00	\$ 80.00 ✓
1 pc	Cone Bearing set ✓ NEC	Damaged	\$ 90.00	\$ 90.00 ✓
1 set	Mirror ✗ NN	Damaged	\$ 45.00	\$ 45.00
2 pcs	Bearing front wheel ✗ NN	Damaged	\$ 40.00	\$ 40.00
1 set	Fork assy ✗ Repair	Bent/distorted	\$ 200.00	\$ 200.00
1 pc	Headlight assy ✗ NN	Grazed & broke	\$ 150.00	\$ 150.00
1 set	Full cover set ✓ CUT	Distorted	\$ 400.00	\$ 400.00 ✓
1 set	Foot rest assy ✓ BT	Bent	\$ 120.00	\$ 120.00 ✓
1 pc	Fork under bracket complete ✗ NN	Distorted	\$ 100.00	\$ 100.00
2 pcs	Foot rest cover ✗ NN	Damaged	\$ 60.00	\$ 60.00
			\$ 1,405.00	\$ 1,405.00 810
Less 10%			\$ 1,264.50	\$ 1,264.50 729

Special Nett Items

1 set	Steering cone & bearing ✗ Repeat Necessary	\$ 180.00	\$ 180.00
		\$ 180.00	\$ 180.00

Total Parts \$ 1,444.50 \$ 1,444.50

Labour Charges

1	Towing fee	\$ 80.00	\$ 80.00 ✗ NN
2	Repair & rebalance front wheel; align steering component	\$ 400.00	\$ 400.00 ✗ NN
3	Renew damage parts & repair affected areas	\$ 250.00	\$ 250.00 150
4	Realign body frame	\$ 400.00	\$ 400.00 ✗ NN
		\$ 1,130.00	\$ 1,130.00

Total Parts & Labours Concluded \$ 2,574.50 \$ 2,574.50

Lump Sum Repair Adjustment (less 20%) \$ 2,059.60 \$ 2,059.60
5 Days

MUHAMMAD REDHA(GM GUSTOBRO WORKSHOP)**HP: 91275273 / gustoenterprise123@gmail.com****879****-20%: 700****2 Days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____