



Section A - Accident Details

Registration Number	SHB118P
Case Reference Number	TAX/07/21/2033
Registration Date	29/12/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SIM KWANG LONG
Type of Accident	Side Swipe
Accident Date and Time	15/7/2021 10:15 AM
Accident Reported Date and Time	15/7/2021 11:59 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111568
Special Instruction to ARC, if any	FRONT LEFT
Prepared Date and Time	15/7/2021 2:17 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$250.00
Total Spray Cost	\$1,494.00	\$450.00
Total Spare Part Cost	\$7,108.71	\$581.48
Total Other Cost	\$830.00	(\$181.48)
TOTAL COST	\$10,277.71 12,368.45	\$1,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	16/07/2021 5:42 PM	16/07/2021 3:51 PM
Signature		
Remarks		lump sum repair / resurvey after repair/ after paint photo .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2108-0004	Invoice Number	
Quotation Date	02.08.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$250.00
Total Labour	\$845.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,494.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$261.48)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$830.00	(\$181.48)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		81170-47500	HEAD LAMP LH	1.00	\$945.20	100.00	\$0.00	Replace	Old Damage
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611--47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		48520-80294	SHOCK ABSORBER FRT/LH	0.00	\$394.20	0.00	\$0.00	Replace	Not Given

R
X
X
X
√
√
X
X
X
R
X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/08/2021

User ID PohSuan

		48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given	X
		48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Not Given	X
		43202-47030	STEERING KNUCKLE LH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Not Given	X
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
		48069-47050	LOWER ARM FRT/LH	0.00	\$625.90	0.00	\$0.00	Replace	Not Given	X
		43330-49185	JOINT ASSY,LWR BALL	0.00	\$195.60	0.00	\$0.00	Replace	Not Given	X
		67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given	X
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X
		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X
		87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
Total					\$9,199.45		\$581.48			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	581.48	
+	250.00	L/S \$1,100/-
+	530.00	
	1,361.48	
	-20%	
	1,089.18	