

SERVICE ESTIMATE

88063 - C00001 SL: SERVICE SALES - PC
Mr Emrys Phua Kang Sheng
22 Jalan Antoi
Seletar Hills Estate
Singapore 809408

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Emrys Phua Kang S

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 21/07/2021
WIP No. . : 36298
Veh.In/Out:
*Tel.No. . : Mobile: 82008190
Reg.No. . : SKE4040B
Reg.date . : 10/01/2017
Mileage ... : 0
Chassis No: SAJBB4AG5HCY39319

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, 2 x 1700	0		4000.00	0		4,000.00	S
	BONNET, HEADLAMP LH, RADIATOR GRILLE, RADIATOR, CONDENSER, ETC						2600	
800	TO SPRAYPAINT ON 2 x 1099	0		3600.00	0		3,600.00	S
	BONNET, FRT BUMPER, 1 LHF FENDER, ETC							
802	TO VACUUM & TOP UP A/C GAS	0		600.00	0		600.00	S
R06	NUMBER PLATE & HOLDER	0		60.00	0		60.00	S
280	TO FOCUS HEADLAMP	0		207.00	0		207.00	S
280	TO CHECK WIRING INCLUDE	0		621.00	0		621.00	S
	RESETTING OF ALL ELECTRICAL MODULES							
	COVER-BUMPER	1.0	EA	2539.40			2,539.40	S
	GRILLE-RADIA	1.0	EA	374.90			374.90	S
	BRACKET-FENDER SUPPO	1.0	EA	29.30			29.30	S
	BRACKET-FENDER SUPPO	1.0	EA	29.30			29.30	S

SERVICE ESTIMATE

88063 - C00001 SL: SERVICE SALES - PC

Mr Emrys Phua Kang Sheng
22 Jalan Antoi
Seletar Hills Estate

Singapore 809408

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Emrys Phua Kang S

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 21/07/2021
WIP No. . : 36298
Veh.In/Out:
*Tel.No. . : Mobile: 82008190
Reg.No. . : SKE4040B
Reg.date. : 10/01/2017
Mileage . : 0
Chassis No: SAJBB4AG5HCY39319

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	PLINTH-NUMBER PLATE / Br	1.0	EA	87.80			87.80	S
	JT2H24589/HEADLAMP L / ? Br	1.0	EA	3599.50			3,599.50	S
	JT2H24576/HEADLAMP R	1.0	EA	3599.50			3,599.50	S
	PANEL-BONNET / ?	1.0	EA	1627.50			1,627.50	S
	JT2H25309/BEAM-BUMPE	1.0	EA	953.90			953.90	S
	INSERT-FOAM	1.0	EA	65.30			65.30	S
	PANEL-FENDER LH x	1.0	EA	1315.40			1,315.40	S
	FINISHER-VENT x	1.0	EA	275.10			275.10	S
	HARNESS	1.0	EA	358.60			358.60	S
	FRAME-SUPPOR RH ?	1.0	EA	453.40			453.40	S
	FRAME-SUPPOR LH ?	1.0	EA	453.40			453.40	S
	RADIATOR ?	1.0	EA	1364.30			1,364.30	S
	FRAME ?	1.0	EA	280.40			280.40	S
	SHIELD-DEFLE ?	1.0	EA	89.50			89.50	S
	SHIELD-DEFLE ?	1.0	EA	92.10			92.10	S
	SHIELD-DEFLE ?	1.0	EA	94.60			94.60	S
	SHIELD-DEFLE ?	1.0	EA	94.60			94.60	S

SERVICE ESTIMATE

88063 - C00001 SL: SERVICE SALES - PC
 Mr Emrys Phua Kang Sheng
 22 Jalan Antoi
 Seletar Hills Estate
 Singapore 809408

GST Reg.No: M28920628X
 0 Page 3
 Inv.No. : B&P
 Inv.date. : 21/07/2021
 WIP No. : 36298
 Veh.In/Out:
 *Tel.No. : Mobile: 82008190
 Reg.No. : SKE4040B
 Reg.date. : 10/01/2017
 Mileage : 0
 Chassis No: SAJBB4AG5HCY39319

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Emrys Phua Kang S

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SHIELD-DEFLE. ?	1.0 EA	113.00			113.00	S
	CONDENSER / OT ?	1.0 EA	1223.00			1,223.00	S
	BODY PANEL SEALANT X ?	1.0 EA	955.20			955.20	S
	ADHESIVE SEALER FL2 ?	1.0 EA	709.60			709.60	S
	PRIMER ?	1.0 EA	185.60			185.60	S

Steve (LKK) 00-AL AL
83228813 EXCERS - ?
P/P, R, Bel Sy
5 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour Total	9,088.00
Parts Total	20,964.20
Package Total	0.00

Gross Total.	30,052.20
Net.....	30,052.20
GST @ 7.0%	2,103.65
Total.....	32,155.85
Paid.....	0.00
Please Pay..	32,155.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated