

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGQ1984Gat Workshop m/s SL

of _____

Insured: GAG 449 D

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £4800

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: SmithVeh No: SGQ1984G Yr Regn: 09/01/07Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Mit Lancer c.c. 1584Colour: blue A/C: Insured / Std / NI / NASp. Reading: 146790 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCS3A7U005107Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ATmaxFront 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/2/21 D.O.I. 19/2/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction SmithWe until 08-01-2022 LTA 2382net 4 2418 have G1423/7/21 2/5 @ 2400 confirmed with Alan.

red: 6595;73%

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

submit to insurers.

Not Authorized
man

19/7/14

1/5 \$2400 4 days

VEHICLE No: SGQ 1984G

NETT ITEM

1PC	FRONT BUMPER	De/turn	698.00	\$801.00
1PC	FRONT BUMPER SIDE RETAINER O/S	Self		\$65.00
1PC	FRONT BUMPER REINFORCEMENT	Self	197.00	\$311.00
1SET	FRONT BUMPSR CLIPS	new		\$50.00
1PC	HEADLAMP O/S	new		\$866.00
1PC	FRONT FENDER O/S	BUL	624.00	\$655.00
1PC	FRONT FENDER INNER SHIELD O/S	Torn	677.00	\$228.00
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	new	182.00	\$50.00
1PC	FRONT FENDER CHROME MOULDING O/S	new	60.00	\$112.00
1PC	FRONT FENDER INNER PANEL O/S	R		\$750.00
1PC	FRONT MUDFLAP O/S	11		\$105.00
1PC	FRONT FENDER QUARTER GARNISH O/S	11		\$55.00
1PC	FRONT FENDER SIGNAL LAMP O/S	11		\$85.00
1PC	BONNET	R		\$808.00
1PC	BONNET INNER RUBBER	Torn	609.00	\$28.00
1PC	FRONT SUPPORT PANEL	R	25.00	\$606.00
				\$5,575.00

TO CHECK WIRING

TO SPRAY RUST PROOFING

TO CONDUCT WHEEL ALIGNMENT

TO DISMANTLE & REFIX FRT DOOR MECHANISM

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

\$50.00	20
\$120.00	60
\$150.00	X
\$100.00	X
\$1,500.00	450
\$1,500.00	750
\$8,995.00	

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2606
102
P-2345-40
L-1280-00
362-40
202
2900