

MCL 3549. 2013 Oct.

TTSampa
Veron
Yamaha Nouvo 135 cc
PMYK 60280D0045594

Front wheel Fender.	cut	95	/
Handlup.	cut	185	/
Handlup Fairing.	cut	195	/
Front LH Signa Lamp.	cut	58	/
Front LH Wing Mirror?		38	/
Handle Grip LH.		25	/
Hand Lever LH.	cut	32	/
Step Board LH.		235	/
Rear LH Foot Rest		45	/
Rear LH Foot Rest Bracket.		90.	x
Main Stand.	Repair	88	x
Rear Engine Cover.	cut	145	/
Rear Fairing LH.	cut	220	/

MCL5549.

Tailor H. ^{MP} 135 X
^M
Stickers. ^{Ne} 50(SN) ✓

Panel Beating. ~~400~~ 200
Spray Painting. ~~400~~ 200
Wiring. ~~50~~ 30

2486.00

List: 1273.
Less 10%: 1145.70.
S.N: 50

Labour: 430
Total: 1625.70
1/5 1K (Nett Value)
04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: