



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV09690/TAN LAI CHOO
	Reg No/Reg Date	SMF4783L / 14/11/201
	Date In/Mileage	19/07/2021/ 0
	Chassis No	GF7W0600275
	Engine No	4J11AA7156
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000	REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA REPAIR ON REAR LH FENDER & REAR FLOOR PANEL							3150.00
E	PNT98000	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL, REAR LH FENDER & REAR FLOOR PANEL							1750.00
E	PNT88000	REMOVE & INSTALL REAR PARKING ASSIST							80.00
E	PNT88000	REPLACE REAR WINDSCREEN GLASS							240.00
M	SUNDRY	TO APPLY WINDSCREEN SEALANT							80.00
E	PNT88000	TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL							150.00
E	PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR							120.00
E	PNT88000	TO CLEAN OF DEBRIS OF SHATTERED GLASS							80.00
M	SUNDRY	PERFORM RUST PREVENTION							40.00
M	SUNDRY	TO APPLY SEALANT ON AFFECTED AREA							80.00
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M	SUNDRY	TO APPLY ZERTONA COATING ON AFFECTED AREA							240.00
M	SUNDRY	TO SUPPLY C & C EMBLEM							40.00
M	SUNDRY	SUNDRIES							30.00
M	LAMP ASSY,COMB,RR LH					1.00	603.00	23.00	464.31

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV09690/TAN LAI CHOO
	Reg No/Reg Date	SMF4783L / 14/11/201
	Date In/Mileage	19/07/2021/ 0
	Chassis No	GF7W0600275
	Engine No	4J11AA7156
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M LAMP ASSY,COMB,RR RH		1.00	603.00	23.00	464.31
M LAMP ASSY,LICENSE PLATE		2.00	34.00	23.00	52.36
M REFLECTOR,TAIL LAMP,RH		1.00	100.00	23.00	77.00
M REFLECTOR,TAIL LAMP,LH		1.00	100.00	23.00	77.00
M LAMP ASSY,TAIL,LH		1.00	506.00	23.00	389.62
M LAMP ASSY,TAIL,RH		1.00	506.00	23.00	389.62
M MOTOR,RR WINDOW WIPER		1.00	505.00	23.00	388.85
M BLADE ASSY,RR WINDOW WIPER		1.00	39.00	23.00	30.03
M ARM ASSY,RR WINDOW WIPER		1.00	64.00	23.00	49.28
M COVER,RR WINDOW WIPER ARM		1.00	10.00	23.00	7.70
M GROMMET,RR WINDOW WIPER		1.00	8.00	23.00	6.16
M BRACKET,RR WINDOW WIPER		1.00	24.00	23.00	18.48
M FACE,RR BUMPER		1.00	1018.00	23.00	783.86
M REINFORCEMENT,RR BUMPER,LH		1.00	79.00	23.00	60.83
M REINFORCEMENT,RR BUMPER,RH		1.00	79.00	23.00	60.83
M BRKT,R/BMPR FACE SIDE,RH		1.00	12.00	23.00	9.24
M BRKT,R/BMPR FACE SIDE,LH		1.00	12.00	23.00	9.24
M EXTENSION,RR BUMPER		1.00	292.00	23.00	224.84
M PANEL,RR END		1.00	326.00	23.00	251.02
M PANEL ASSY,TAILGATE		1.00	989.00	23.00	761.53
M W/STRIP,TAILGATE OPENING		1.00	213.00	23.00	164.01
M HINGE,TAILGATE		2.00	46.00	23.00	70.84
M GARNISH,TAILGATE		1.00	496.00	23.00	381.92
P FASTENER,WINDSHIELD		4.00	6.00	23.00	18.48
M DAM,TAILGATE,UPR		1.00	13.00	23.00	10.01
M GLASS,TAILGATE WINDOW		1.00	657.00	23.00	505.89
M DAM,TAILGATE SIDE		2.00	27.00	23.00	41.58
M STOPPER,WINDSHIELD GLASS		2.00	3.00	23.00	4.62
M DAM,TAILGATE,LWR		1.00	41.00	23.00	31.57
M STRIKER,TAILGATE LATCH		1.00	20.00	23.00	15.40
M LATCH,TAILGATE		1.00	385.00	23.00	296.45
M TRIM,TAILGATE		1.00	329.00	23.00	253.33
M MARK,OUTLANDER		1.00	95.00	23.00	73.15

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<b>Cust No/Name</b>	KCV09690/TAN LAI CHOO
	<b>Reg No/Reg Date</b>	SMF4783L / 14/11/201
	<b>Date In/Mileage</b>	19/07/2021/ 0
	<b>Chassis No</b>	GF7W0600275
	<b>Engine No</b>	4J11AA7156
	<b>Make/Model</b>	MIT/19MY OUTLANDER 2.0 MODERN(995)
	<b>Colour/Trim</b>	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TRIM,RR END	1.00	113.00	23.00	87.01

# Estimate

Confirm &amp; accepted by

	<b>Nett</b>	<b>12,760.37</b>
7% GST on	12760.37	893.23
<b>Total Payable</b>		<b>13,653.60</b>

\_\_\_\_\_  
 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.