

KURU & CO

Advocates & Solicitors

UEN No. 53130937A / GST Registration No: M90366606R

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727

Tel: 65322 009 (5 lines) / Fax: 65322 007 (Our fax no. is not for service of court documents)

Our ref: L.21.0466.pl
(Please quote our reference when replying)

19 July 2021

BY CERTIFICATE OF POSTING

RH Synergy (S) Pte. Ltd.
7030 Ang Mio Kio Avenue 5
#02-22 Northstar @AMK
Singapore 569880

(Yr ref: GBB 6935D)

BY EMAIL ONLY

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

(Yr ref: GBB 6935D)

Dear Sirs,

ACCIDENT INVOLVING SKB 4960L AND GBB 6935D ON 09.06.2021 AT/ALONG EUNOS LINK

We act for **Mohamed Ukkas Maricar Bin Hussain**, owner of vehicle registration number **SKB 4960L**.

We are instructed to claim for damages against you in connection with the above-captioned road traffic accident involving our client's vehicle and your vehicle registration number **GBB 6935D**.

We are instructed that the accident was caused by your/your driver's/your insured's negligent driving and/or management of your/your insured's vehicle. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:

Cost of repairs	\$10,700.00
Loss of use	\$ 960.00
Survey fee/s	\$ 896.00
LTA fee/s	\$ 7.49
Incidentals (Inclusive of GST)	\$ 53.50
Cost at this stage (Inclusive of GST)	\$ 1,070.00

Enclosed are the supporting documents for your perusal:

Pre-repair Notification letter

Our client's SAS report

Your insured's LTA search

Repair Bill

Survey report, invoice and **219 colored photographs**

LTA receipt

Our ref: L.21.0466.pl
(Please quote our reference when replying)

19 July 2021

**ACCIDENT INVOLVING SKB 4960L AND GBB 6935D ON 09.06.2021
AT/ALONG EUNOS LINK**

We have on 11.06.2021 notified your insurer of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurer on 14.06.2021.

Should you have a counterclaim against our client arising out of the accident, you are required to send us a letter giving full particulars of the counterclaim with all relevant supporting documents within **8 weeks** from your receipt of this letter.

Please also note that you or your insurer should send us an acknowledgement of receipt of this letter within **14 days** of your receipt of this letter, failing which our client will have no alternative but to commence proceedings without further notice to you or your insurer.

Yours faithfully,



Encl.

N.B. Supporting documents are forwarded only to your insurer BY EMAIL

**Cc. NTUC Income Insurance Co-Operative Limited (Mutual client– SKB 4960L) /
BY EMAIL**

Please do not prejudice our mutual client's claim in whatsoever way. Meanwhile, we would be obliged if you could let us have a complete set of third party's SAS/police report if you have received a copy of same for our attention.

Cc. client

Lonpac Our ref: L21.0466.cj / ACCIDENT INVOLVING ON SKB 4960L & GBB 6935D ON 09/06/2021 AT/ALONG EUNOS LINK NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

From: Kuru & Co (kurulegal@yahoo.com.sg)

To: mt_claim@lonpac.com; geraldpo@lonpac.com

Date: Friday, 11 June 2021, 2:38 pm SGT

Dear Sirs

**ACCIDENT INVOLVING ON SKB 4960L & GBB 6935D ON 09/06/2021
AT/ALONG EUNOS LINK
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **MOHAMED UKKAS MARICAR BIN HUSSAIN** whose motor vehicle registration number **SKB 4960L** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.



21 0466 SAS REPORT.pdf
6.3MB



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/06/2021 15:08 (SGT)
Date of Accident	09/06/2021 21:25 (SGT)
Exact Location of Accident	Eunos Link, Singapore
Additional Location Information	Eunos Link (below PIE flyover) towards Marine Parade
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB4960L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Mohamed Ukkas Maricar Bin Hussain
NRIC No	SXXXX758H
Email Address	mdukkas@gmail.com
Mobile Phone No	(Phone) +65-83303306
Alternative Phone No	(Home) +65-83303306

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Wish
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5122353169
Cover Note Number	

DRIVER

Name of Driver	Shahul Hameed Athabiya Nachiar
NRIC No	SXXXX005C

Date Of Birth	11/01/1988
Occupation	Indoor
Date Of Driving Pass	27/09/2014
Driving experience	6 YEARS AND 9 MONTHS
Gender	Female
Mobile Number	(Phone) +65-83303306
Alt. Phone Number	-
Email Address	mdukkas@gmail.com
Address	Blk 3A Upper Boon Keng Road #03-602
Address complement	-
Postcode	381003
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Hameed Fathima Kani
Gender	Female

PASSENGER 2

Name	Muhammad Mohaiydeen
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB6935D
Vehicle Manufacturer	Toyota

Vehicle Model	Dyna
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	Sethu Pandi Ayyachamy
Work Permit No	GXXXX981P
Contact Number	(Phone) +65-83495992
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Hameed Fathima Kani
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKB4960L
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	Muhammad Mohaiydeen
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKB4960L
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

I WAS DRIVING ALONG LUNDA LINK TOWARD S. MARINE PARADE. AT THE JUNCTION A WHITE DIE SELVER I WAS APPROACHING TRAFFIC JUNCTION. I STOPPED MY CAR AFTER A FEW SECONDS LATER, A LORRY (GIBB 69352) CAME FROM BEHIND AND CRASHED ON TO THE REAR OF MY CAR WITH A STRONG IMPACT. THE REAR PORTION OF MY CAR WAS SERIOUSLY DAMAGED.

I FELT PAIN ON BOTH MY HANDS, LEFT LEG AND NECK FELT DIZZY AFTER THE CRASH / KNOCK. I WOULD SEE DOCTOR IF NEEDED.

MY MUM, HAMMED FATHIME KANI, FELT SOME BACKACHE AND BODY ACHES. WE WOULD MONITOR HER BEFORE CONSULTING DOCTOR TREATMENT.

MY BABY, MUHAMMAD MUHAMMAD / RIED UP ON THE KNOCK, NO SIGNS OF VIOLENCE. WE WILL MONITOR THE BABY IF NEED TO SEE DOCTOR.

THE LORRY DRIVER, SEEDU KANDI, GUYA CHAMU SIN NO: 073949812 IDENTIFIED HIS MISTAKE AND AGREED TO CLAIM AGAINST HIS INSURANCE FOR THE WHOLE DAMAGES INCURRED.

Declaration

We declare the foregoing particulars are true in every respect.

10/06/2021
Policyholder's Signature / Date & Time

10/06/2021
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

<p>14. <u>10/06/2027</u></p> <p>Policyholder's Signature: <u>[Signature]</u> Date & Time</p>	<p>10/06/2027</p> <p>Driver's Signature (if driver is not the policyholder): <u>[Signature]</u> Date & Time</p>	<p>Witnessed by Reporting Centre Personnel</p> <p><u>[Signature]</u></p>
--	---	--

Sketch Plan















Enquire Vehicle Owner Details (As At 09 Jun 2021 / 21:25:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

200608152K

Owner Name:

RH SYNERGY (S) PTE. LTD.

Registered Address Type:

**Private Residential (Condo Apt or House) /
Shopping / Office Complexes**

Registered Block/House No.:

7030

Registered Street Name:

ANG MO KIO AVENUE 5

Registered Unit No.:

02 - 22

Registered Building Name:

NORTHSTAR @ AMK

Registered Postal Code:

569880

Vehicle Insurance Details

Vehicle No.:

GBB6935D

Make Description/Model:

TOYOTA / DYNA 150 MANUAL 3SEATER

Insurance Company Name:

LONPAC INSURANCE BHD

Enquire Vehicle's Insurance Particulars (As At 09 Jun 2021 / 21:25:00)

Vehicle No.:

GBB6935D

Make Description/Model:

TOYOTA / DYNA 150 MANUAL 3SEATER

Insurance Company Name:

LONPAC INSURANCE BHD

Business Transaction Reference No.:

20210611141711538975

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 11 Jun 2021 14:17:18

Copyright © Land Transport Authority of Singapore 2021

RS AUTOMOTIVE PTE LTD

Workshop : Blk 3006 Ubi Road 1 #01-394 Singapore 408700
Mailing : 109 Pasir Ris Grove, #09-23 The Palette Singapore 518199
Tel No. : 67483032 Fax No. : 67499469
E-Mail : rsautomotive@yahoo.com.sg
Website : www.rsautomotive.com.sg
Tax Reg. No. : 201230654Z Buss. Reg. No. : 201230654Z

MOHAMED UKKAS MARICAR BIN HUSSAIN

Tax Invoice : 64127

Contact : 82254567

Invoice Date : 07/07/2021
Vehicle Num. : SKB 4960 L
Make/Model : TOYOTA WISH
Mileage(Km) :
PO/WO/RO# :
Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		TOTAL REPAIR COST	10,000.00	10,000.00

SingDollars : Ten Thousand Seven Hundred Only

E. & O.E.

Total S\$: 10,000.00
GST @ 7% S\$: 700.00
Amount Due S\$: 10,700.00
=====

Terms : Cash

Customer's Signature/Co. Stamp

for RS AUTOMOTIVE PTE LTD

*Goods Sold are not refundable for cash and No Claim will be considered after 7 days from date of job

*Interest Rate of 1 5% per month will be imposed on overDue account(s) or should RS were to incur expenses including legal fees, interest charges, debt collection fees, etc., all these will be billed to you for settlement

Our reference: 21-7850

Date: 20/6/2021

INVOICE NO. 7850

Mohamed Ukkas Maricar Bin Hussain

c/o RS Automotive Pte Ltd

3006 Ubi Road 1 #01-394

Kampong Ubi Industrial Estate

Singapore 408700

Registration No. **SKB4960L**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 896.00
Total amount			\$ 896.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.



L. L. Tan (Ms)

Principal Consultant

Subsidiaries of Impact Analysis Consultant:

● Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd
● IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd
www.iaconsulting.sg

Our reference: 21-7850

Date: 20/6/2021

c/o RS Automotive Pte Ltd
3006 Ubi Road 1 #01-394
Kampong Ubi Industrial Estate
Singapore 408700

Dear Sirs

RE: **Road Traffic Accident on 9/6/2021**
Mohamed Ukkas Maricar Bin Hussain

In accordance with your instructions received in this office on **11/6/2021**, we made arrangements to examine the vehicle on **11/6/2021** at above-mentioned address. The following data was recorded:

Vehicle details

Make	Toyota	Registration	SKB4960L
Model	Wish	Chassis	ZGE200067868
Colour	Blue	Gearbox	Auto
Odometer	153034km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195/65R15	85% Triangle
Front right	195/65R15	85% Triangle
Rear left	195/65R15	85% Michelin
Rear right	195/65R15	85% Michelin

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of **\$10,000.00** and **7** working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Our reference 21-7850

Date 20/6/2021

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Tail gate	1	crushed	1198.76	1198.76
Tail gate inner trim	1	deformed	215.60	215.60
Tail gate inner lock	1	damaged.jammed	388.40	388.40
Tail gate weather strip	1	ripped.nec	280.60	280.60
Tail gate logo	1	necessary	68.50	68.50
Tail gate outer moulding	1	bent	245.80	245.80
Tail gate windscreen glass	1	shattered	1455.60	1455.60
Tail gate windscreen moulding @\$77.50	4	necessary	155.00	155.00
Tail gate wiper motor	1	malfunction	355.60	355.60
Tail gate wiper arm	1	bent	145.80	145.80
Tail gate wiper blade	1	serviceable	105.00	0.00
Tail gate wiper arm cover	1	damaged	41.00	41.00
Tail gate damper @\$175.00	2	stiffened	350.00	350.00
Tail gate spoiler	1	damaged	388.45	388.45
Tail gate reflector @\$235.00	2	lh cracked rh intact	470.00	235.00
Tail gate plate "valve metric"	1	necessary	91.40	91.40
Rear bumper	1	deformed	985.60	985.60
Rear bumper energy absorber @\$75.50	2	lh bent rh reuse	151.00	75.50
Rear bumper side retainer @\$59.90 (long)	2	lh damaged rh reuse	119.80	59.90
Rear bumper side retainer @\$38.50 (short)	2	lh damaged rh reuse	77.00	38.50
Rear bumper reflector lh	1	cracked	75.20	75.20
Tail lamp @\$378.60	2	broken	757.20	757.20
Tail lamp panel @\$285.10	2	repair	570.20	0.00
Rear end panel	1	bent	498.78	498.78
Rear end panel top garnish	1	deformed	265.60	265.60
Rear fender @\$1253.80	1	repair.respray	2507.60	0.00

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Our reference 21-7850

Date 20/6/2021

Rear fender air vent lh	1	broken	115.20	115.20
Rear fender inner trim @\$585.50	2	broken	1171.00	1171.00
Rear fender inner panel lh	1	bent	231.50	231.50
Rear floor panel	1	repair	986.80	0.00
Rear exhaust pipe	1	bent	602.40	602.40
Rear spare tyre holder	1	reuse	285.70	0.00
Sub- Total costs			15356.09	10491.89
Percentage discount : 25%			3839.02	2622.97
Sub-Total costs for parts			11517.07	7868.92

Special Nett Items:

Rear bumper clips @\$5.00	8	necessary	40.00	40.00
Tail lamp clips @\$5.00	6	necessary	30.00	30.00
Rear end panel top garnish clips @\$5.00	2	necessary	10.00	10.00
Tail gate windscreen sealant	1	necessary	60.00	60.00
Reverse camera	1	check. Refix	350.00	0.00
Rear number plate	1	bent	50.00	50.00
Tail gate keyless sensor	1	broken	220.00	220.00
Rear reverse sensor	1	malfunction	280.00	250.00
Rear end panel sealant	1	necessary	40.00	40.00
Rear floor panel insulation	1	necessary	60.00	60.00
Sub- Total costs			1140.00	760.00

Parts Repair

*	*	*	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			12657.07	8628.92

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Our reference 21-7850

Date 20/6/2021

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	27	\$ 1,215.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 1,250.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 60.00
Wiring and bulb checking	\$ 45.00	1	\$ 45.00
Remove and replace tail gate windscreen glass (2-man job)	\$ 45.00	3.5	\$ 157.50
Remove and refix upholstery to facilitate repair	\$ 45.00	2	\$ 90.00
Transfer tail gate mechanism	\$ 45.00	2	\$ 90.00
Conduct water leak test for rear portion associated repair works	\$ 45.00	1	\$ 45.00
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$ 45.00	1.7	\$ 76.50
Remove and replace rear exhaust system	\$ 45.00	2	\$ 90.00
Remove and replace rear reverse camera & conduct distance safety setting	\$ 45.00	1.7	\$ 76.50
Total labour cost			\$ 3,195.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$8,628.92	
Further discount	20%	\$1,725.78	
Recommended cost of parts replacement		\$6,903.13	(1)
Labour Cost Calculation (See section B)		\$3,195.50	(2)
Total Repair Cost (Round off to hundred)		\$10,000.00	(1) + (2)

We would recommend a sum of **\$10,000.00** and **7** working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma. Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsulting.sg






















































































































Thank you

Khoo Ling Ling has successfully logged out.

Your last login date and time was 11 Jun 2021, 14:16:01.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	GBB6935D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	11 Jun 2021 / 14:17:11