



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21006652/Vvf3e2-1	
			Date: 19/08/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 6935D	Veh. Inspected	SKB 4960L
	Policy No.	Z21VC05007341	Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/0024646	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	19/07/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8X A	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	ZGE200067868	Colour	BLUE
	Odometer	153034 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/06/2021	Inspection Date	14/06/2021
	Survey held at	RS AUTOMOTIVE WORKSHOP BLK 3006 UBI ROAD 1 #01-394 SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	