

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21007755/KTCN2**Date:** 08/02/2022**REFERENCE**

Insured/Claimant: SHAZAWANI BEGUM BINTI ABDUL KARIM Policy No: DMPCSNW00177272000  
Date of Loss: 15/05/2021 Nature of Claim: OD Claim No: SNM21D204248/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV4623G**  
Make & Model: BMW 520I, 2.0 (A) Engine No: B7520540N20B20B  
Reg. Date: 28/08/2013 (Man. Year: 2013) Chassis No: WBAXG12090D292184  
Colour: Metallic Black Odometer: 88156 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: S\$56,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 245/40R19 Rear Tyre Size: 275/35R19  
Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm  
Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	59,894.20	24,452.90	35,441.30	59.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,724.50	2,938.50	1,786.00	37.80
Paintwork Labour	742.34	742.34	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>65,361.04</b>	<b>28,133.74</b>	<b>37,227.30</b>	<b>56.96</b>
<b>- Excess (S\$)</b>	0.00	1,250.00	-1,250.00	
<b>(S\$)</b>	65,361.04	26,883.74	38,477.30	58.87
<b>+ GST 7.00/7.00% (S\$)</b>	4,575.27	1,881.86	2,693.41	58.87
<b>Nett Amount (S\$)</b>	<b>69,936.31</b>	<b>28,765.60</b>	<b>41,170.71</b>	<b>58.87</b>

**INSPECTION**

Date of Assignment: 19/07/2021 Present Location: Ding Auto Pte Ltd (HQ)  
Date Inspected: 21/07/2021 Inspected At: BLK 10 #01-20 SIN MING IND EST SEC C  
SINGAPORE 575645  
Estimated Period of Repair: 14.0 days REPAIRER: DING AUTO PTE LTD

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2022)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV4623G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		59,894.20 F	*24,452.90 F
						F=Franchise part.
Total Parts (S\$)					59,894.20	24,452.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	Total Paint Labour	New	441.00	441.00
2	Total Paint Materials	New	301.34	301.34
<b><u>Labour Items</u></b>				
3	Total Panel/Mechanical Labour	New	4,724.50	2,938.50
<b>Gross Labour Cost (\$\$)</b>			<b>5,466.84</b>	<b>3,680.84</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >