

SLX 8542G.

TPEQ

Honda Shuttle

Denise

GP71208335.

Front Number Plate.	2	30(SW) X
Front Number Plate Holder	x4 Nec	30(SW) X.
Front Bumper. Distorted.		1050 ✓
Front Bumper Clips.	Nec	30(SW). ✓
Front Bumper Side Holder x 02	Damd	28 x 1 = 56. ✓
Front Bumper Reinforcement	Distorted	420.90. ✓
Front Bumper Lower Grille.	Dehd	152 ✓
Front Bumper Fog Lamp LH	Cruld	289.40. ✓
Front Bumper Fog Lamp Lower LH.	Dehd	148.20. ✓
Front Bumper Fog Lamp Top Moulding LH.	Dehd	56. ✓
Front Grille	Cruld	395.40 ✓
Front Grille Logo	Nec	39.40. ✓
Front Grille Chrome Moulding.	x4 Nec	231.80 X
Front Grille Clips.	Nec	20(SW). ✓
Front Grille Inner Bracket.	Cruld	65.60 ✓

SLX 8542G.

Headlamp x 02	cracked	2250 x 2 = 4500 ✓
Headlamp lower Bracket x 02	LH cracked	91.8 x 2 = 183.60 91.80
Front Support Panel	Bricked	749.20 ✓
Front Support Panel Top Cover	} 2nd over	95.90 x
Front Support Panel Top Cover Clips.		20(SW) x.
Front Fender x 02	LH Bricked	483.5 x 2 = 967 483.50
Front Fender Inner Shield LH.	torn	145. ✓
Air Cond Condensers	Warpped	1082 ✓
Air Con Fan Cowling.	Bricked	121.90. ✓
Air Con Fan Motor	} 2nd over	330 x
Air Con Fan Blade.		78 x
Radiator	Dented	1540.40 ✓
Radiator Fan Cowling.	Cracked	115.50. ✓
Radiator Fan motor	} 2nd over	219.40. x
Radiator Fan Blade.		78.40 x
Air Duct.	Dented	80.60 ✓
Air Guide x 02.	2nd over	34.5 x 2 = 69 x
Hybrid Emblem x 02	} 2nd over	68 x 2 = 136 ✓
Coolant		80(SW) ✓

SLX 8542G.

Panel Beating

~~1800~~ 1200

Spray Painting.

~~1600~~ 1000

Wiring.

~~100~~ 30

To remove condenser and to top up air (gas). ~~120~~ 60

To remove radiator and to top up coolant. ~~120~~ 60

List: 11718.80. Labour: 2350

Len 20%: 9375.04. Total: 11835.04

S.N: 110. H/s: 9.4K.

08 Days.

17234.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: