

REC. BY:

ASS. REC. BY:

Hg



KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction

KGC WORKSHOP
Sincere • Secure • Satisfaction
14 Ang Mo Kio St. 63, Block B (S) 569116
Tel : 6453 6279 / 6456 5410
Email : contact@kgcworkshop.com.sg

*Not Withheld
Recovery After Paint
3 days
L1 Day @ 455.00*

Part(s) \$14,643.22
+ Labour @ 2,460.00
\$ 7,103.22
- 20%
\$ 5,682.58
= Lump sum ~~\$5,650.00~~

Sh Keng Leong
Ang Mo Kio St 63
Block B
Singapore 569116

TP
Date: 16/7/2021
No of Page: 1/2

Registration No: SGY 6886G
Incident Date: 12-Jul-21
Ref: TP

Model: BMW 520I
Chassis No: WBAJR12010CD55352
Engine Capacity:

No	Qty	Items	Unit Price	Amount
	1	Front Bumper	\$ 1,384.80	\$ 1,384.80 X
	1	Front bumper retainer RHS	\$ 36.80	\$ 36.80 X
	1	Front Bumper Lower Grille RHS	\$ 117.00	\$ 117.00 X
	1	Front bumper Lower Grille (outer) RHS	\$ 69.00	\$ 69.00 X
	1	Front Fog Lamp Cover	\$ 80.00	\$ 80.00 X
	1	Front Fender RHS	\$ 938.00	\$ 938.00 X
	1	Headlamp Assy RHS <i>4879.55</i>	\$ 4,887.60	\$ 4,887.60
	2	Front parking sensor x2 (RHS)	\$ 205.00	\$ 410.00 X
			\$ 7,923.20	
			-5%	\$ 396.16
Total for spare parts			\$	7,527.04

*\$4,887.60
5%
\$4,643.22*

Special Nett

1 set	Front Bumper Clips	\$ 50.00	\$ 50.00 X
Total for SP		\$	50.00
Sub-Total for Parts :		\$	7,577.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

EC. BY:

ASS. REC. BY:



KGC WORKSHOP PTE LTD
Sincere • Secure • Satisfaction

Since 1997

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		800.00 <i>200</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas		800.00 <i>440</i>
3		To perform paint protection film(ONERPRO) over the bumper and fender <i>and coating as well (bill attached)</i>		<i>(Bill)</i> 1,800.00 <i>400</i>
4		To remove and refit reverse sensor & conduct distance safety setting		<i>na</i> 100.00 <i>X</i>
5		To check wiring system to facilitate repair and refit the same		100.00 <i>20</i>
6		Apply rust proofing on the adjacent panels		<i>na</i> 100.00 <i>X</i>
			<u>\$2,460.00</u>	
TOTAL AMOUNT :				<u>3,700.00</u>
OVERALL COST :				<u>11,277.04</u>

20

86

IA
IA

7